AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 09 Apr 2026 | Lot size: 11,925 m² | Confidence: High

Executive Summary

A current pond is present on-site. Historical imagery also indicates at least one additional former or altered pond / wet depression on-site. Site disturbance or possible fill-related ground modification is also visible. Adjacent off-site water features were identified and treated as contextual only.

Assessment Boundary

Current north-up image showing the drawn lot assessment boundary used for this screening.

Key Flags

Former Water Features	**High**
Historical imagery indicates a current pond and at least one additional former pond / altered wet depression on-site.	

Fill / Disturbance	**Elevated**
Recent on-site disturbance and possible fill-related ground modification are visible.	

Recommendation

A current pond is present on-site and historical imagery also indicates at least one additional former or altered pond / wet depression. Detailed geotechnical investigation is strongly recommended.

Current Site Image

North-up current imagery. Polygon shown for site reference. Any visible disturbance is highlighted only if clear.

Source: mapbox_bbox_site

Historical Evidence

Best historical image showing the clearest former water feature evidence.

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | 1995-06-18

Later Comparison Image

Later imagery used to check whether the historical water feature remains visible or appears altered.

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | 2021-07-17

Limitations & Disclaimer

- Lower resolution in 1995 imagery reduces clarity of some feature boundaries.
- No subsurface data; infilled pond status is inferred from surface changes.

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.