# AI SITE HISTORY REPORT (Beta)

| | |
|---|---|
| **Address** | 502 Church Road, Taigum QLD |
| **Generated** | 17 Apr 2026 |
| **Lot size** | 11,925 $m^2$ |
| **Years scanned** | Current imagery only |
| **Confidence** | Medium |

### Preliminary Screening Notice

This report is generated using automated interpretation of available aerial imagery and is intended for preliminary site screening purposes only.

While reasonable effort has been made to identify visible indicators such as ponds, historical water features, and site disturbance, not all features may be detected or accurately interpreted.

Users are strongly encouraged to independently review historical imagery (e.g. Google Earth) and obtain a detailed geotechnical investigation in accordance with AS2870 prior to design, construction, or purchase decisions.

## Current Site Overview

Figure 1: Current site overview used for automated screening.

## Executive Summary

A current pond feature is present on-site. Site disturbance or possible fill-related ground modification is also visible.

## Key Site Risks

| | |
|---|---|
| Current Pond / Wet Area | High |
| A current pond or pond-like depression is present on-site and should be treated as a relevant moisture-related geotechnical risk. | |

| | |
|---|---|
| Fill / Disturbance | Elevated |
| Existing building / hardstand footprints and associated on-site disturbance are visible, indicating prior localised ground modification. | |

## Recommendation

A current on-site water feature is present and should be considered in geotechnical assessment. Detailed geotechnical investigation is strongly recommended.

# Current Site Image

North-up current imagery with the submitted lot boundary shown for site reference.

Source: mapbox_bbox_site

# Geotechnical Risk Summary

The following preliminary risk commentary is based on interpreted site history features identified from available aerial imagery.

## Disturbance / Fill Risk

**ELEVATED**

Existing building / hardstand footprints and associated site disturbance indicate prior localised ground modification may have occurred. These areas can be associated with regrading, hardstand construction, service installation, slab preparation, or localised fill placement. The origin and composition of any modified ground remain unknown at this stage and may contribute to variable near-surface conditions, foundation performance issues, or differential settlement if not properly assessed in accordance with AS2870.

## Pond / Wet Area Risk

**HIGH**

The presence of a current pond or pond-like depression within the site indicates localised moisture influence and potential variability in subsurface conditions. Such features are commonly associated with elevated moisture contents, soft or compressible soils, and conditions that may contribute to ground movement. These areas may remain seasonally wet or act as surface water collection points, which can impact foundation performance and are relevant to site classification considerations in accordance with AS2870.

# Limitations & Disclaimer

## Limitations

- No historical imagery available to screen former water features
- Low confidence on disturbance extent due to limited temporal data
- No historical imagery to confirm former water presence or disturbance progression.
- Low confidence in water feature detection due to imagery resolution and shading.

## Disclaimer

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.