AI SITE HISTORY REPORT

502 Church Road, Taigum QLD 4018

Generated 07 Apr 2026 | Lat -27.333162, Lng 153.048970 | Confidence: Medium

Executive Summary

The site at 502 Church Road, Taigum QLD 4018 contains one distinct on-site water feature, a pond (Pond A), visible in historical imagery from 1995 through to the present. The pond has gradually shrunk and now has reduced visible open water with increasing vegetation. There are no other distinct water bodies on site or substantial disturbances visible within the lot boundary. Adjacent context includes a creek and open fields but no water bodies immediately adjacent the site.

On-site: One distinct pond (Pond A) centrally located within the site boundary. Initially large and filled with water in historical images from 1995 to 2011, the pond appears to decrease in water extent and increase in vegetation cover from 2015 onwards, with the current imagery showing very little open water. No significant fill, disturbances, or constructed pads observed within the site boundary. Tracks or cleared areas near the pond's edge inside the polygon are minimal and unstructured.

Adjacent / context: Adjacent to the east boundary is Church Road and beyond that agricultural fields. To the north-east, off-site, lies Cabbage Tree Creek, visible in wide context imagery but not immediately adjacent. No other ponds or dams directly adjacent to the lot boundary are observed. Surrounding context is mostly open grassland with sparse trees.

Site Details

Address	502 Church Road, Taigum QLD 4018
Location source	polygon
Latitude / Longitude	-27.333162, 153.048970
Site bbox	45.7 m × 47.2 m
Context bbox	99.7 m × 101.2 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	Elevated	Presence of a single pond visible consistently in historical imagery dating to at least 1995. No multiple ponds observed.
Vegetation / land change	Low	Minimal clearings visible within the lot boundary, mostly consistent grassy areas and slight disturbed ground around pond edges.
Fill / disturbance	Low	No obvious evidence of earthworks, fill pads, or significant disturbance within the lot boundary.

Flag Summary

Potential Fill / Disturbance	**Low**
No obvious evidence of earthworks, fill pads, or significant disturbance within the lot boundary.	
Former Water Features	**Elevated**

Presence of a single pond visible consistently in historical imagery dating to at least 1995. No multiple ponds observed.

Vegetation / Land Change	Low
Minimal clearings visible within the lot boundary, mostly consistent grassy areas and slight disturbed ground around pond edges.	

Screening Outcome

The site contains one historic pond with decreasing water extent and increasing vegetation, indicating a likely former dam or retention pond. No major disturbance or multiple water bodies are evident. Potential for localized geotechnical issues associated with pond sediments and moisture variability.

Distinct Feature Review

Feature	Type	Relation	Status	Notes
Pond A	pond	on_site	appears_to_reduce	Single distinct pond visible within site boundary showing decline in open water area over time with increasing vegetation.

Feature Timeline

Pond A — 1995: Clear open water pond, circular, well-defined.

Pond A — 2005: Open water maintained, no obvious changes in size or shape.

Pond A — 2011: Still open water pond with dense vegetation around edges.

Pond A — 2015: Open water visibly reduced, increasing aquatic vegetation present.

Pond A — 2019: Pond water area further reduced, more vegetation cover.

Pond A — 2021: Mostly vegetated with minimal open water remnants.

Pond A — Current: Very limited open water, almost fully vegetated basin.

Detailed Findings

Visible Observations

• One on-site pond (Pond A), roughly circular with vegetated edge berm.

• Pond A shows open water in 1995, 2005, and 2011 imagery.

• Vegetation increases inside Pond A from 2015 onward, open water reduces.

• No other distinct water bodies inside the lot polygon.

• Minimal ground disturbances or earthworks visible within site boundary.

• Adjacent land to east is cleared agricultural land and Church Road.

• Cabbage Tree Creek visible off-site to north-east, outside lot boundary.

Overall Change Timeline

1995-2011: Pond A contains substantial open water, well-defined circular shape, consistent size.

2015-2021: Pond A shows gradual reduction in open water extent and increase in vegetative cover inside pond basin.

Current: Pond A largely vegetated with only small remnants of open water visible within the former pond area.

Possible Geotechnical Implications

• Pond area with historic water presence may have soft, saturated or organic soils beneath.

• Reduced pond water and increased vegetation could indicate sediment infill or organic matter accumulation affecting soil stability.

• Localized moisture variation near the pond basin may impact foundation performance if development occurs close to pond limits.

Targeted Investigation Focus

• Soil sampling and strength testing within vegetation-filled pond basin.

• Assessment of moisture content and organic soil presence.

• Evaluation of ground stability adjacent to pond edges.

• Identification of potential fill or disturbed zones near pond margins.

Recommended Follow-Up

• Conduct soil boreholes or cone penetration tests near and within the pond basin area to assess soil conditions.

• Perform geotechnical site inspection focusing on moisture variations and organic content in pond sediments.

• Investigate drainage and surface water management plans considering historic pond location.

• Review any available local council or environmental site history reports for further details.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_4 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

historical_qld_followup_6 — 2021 (2021-07-17)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 2

Limitations & Disclaimer

- Imagery resolution limits detailed interpretation of minor disturbances or exact soil conditions.
- Water content and subsurface conditions cannot be confirmed by aerial imagery alone.
- Vegetation and seasonal timing may affect visible pond water extent.

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.