



G=11 C=12 H=11 app=0.74 gpp=1.52 aff=0.86 gff=0.73 $\kappa=4.01$ $\gamma\tau_w=-1.000$

Good / Bad curvature ($C = \kappa \cdot \nabla p$)



Curvature drive along $\psi_N = 0.95$



$C = 0$ loci across flux surfaces

