



G=12 C=17 H=7 app=0.60 gpp=0.82 aff=2.41 gff=2.13 $\kappa=3.98$ $\gamma\tau_w=-1.000$

Good / Bad curvature ($C = \kappa \cdot \nabla p$)



Curvature drive along $\psi_N = 0.95$



$C = 0$ loci across flux surfaces

