



G=13 C=10 H=12 app=2.03 gpp=0.93 aff=0.94 gff=1.80 $\kappa=5.00$ $\gamma\tau_w=-1.000$

Good / Bad curvature ($C = \kappa \cdot \nabla p$)



Curvature drive along $\psi_N = 0.95$



$C = 0$ loci across flux surfaces

