



G=14 C=12 H=6 app=0.74 gpp=1.76 aff=0.98 gff=0.62 $\kappa=4.96$ $\gamma\tau_w=-1.000$

Good / Bad curvature ($C = \kappa \cdot \nabla p$)



Curvature drive along $\psi_N = 0.95$



$C = 0$ loci across flux surfaces

