

Section 1: Neighborhood Infrastructure Profiles

- The Casbah (Medina): * Access Constraints: Extremely narrow streets (1.5m to 3m wide). No heavy vehicle access for fire trucks over 5 tons.
 - Structural Vulnerability: High risk of "Domino Effect" collapses due to shared load-bearing walls.
 - Critical Utility: Aging lead water pipes (1920s era) and high-density electrical cabling.
- Alger Centre (European Quarter): * Access Constraints: High traffic congestion on *Rue Didouche Mourad*.
 - Infrastructure: Extensive underground gallery network for electricity and fiber optics.
- El Harrach / Bab Ezzouar:
 - Vulnerability: Flood-prone during heavy rainfall due to proximity to the Oued El Harrach.
 - Infrastructure: Modern industrial zones but high-pressure gas pipelines near residential sectors.

Section 2: Emergency Response & Prioritization Matrix (SOP-2026)

[SOP-TYPE: GAS LEAK]

- Initial Priority: CRITICAL / IMMEDIATE
- Risk Factors: Explosion, asphyxiation, fire escalation.
- Mandatory Response Protocol:
 1. Establish a 50-meter safety perimeter immediately.
 2. Contact Sonelgaz Emergency (Direct: 3303).
 3. Strict Prohibition: No electrical switches, mobile phones, or motorized vehicles to be operated within the leak zone.
 4. Evacuate all residents in downwind buildings.

[SOP-TYPE: STRUCTURAL FAILURE / CRACKS]

- Initial Priority: HIGH
- Risk Factors: Building collapse, domino effect on adjacent structures (especially in Casbah/Bab El Oued).
- Mandatory Response Protocol:
 1. Deploy a Technical Assessment Team from the Direction de l'Urbanisme.
 2. Immediate evacuation if cracks exceed 2cm or are diagonal on load-bearing walls.
 3. Cordon off the street to prevent vibration from heavy traffic/trucks.
 4. Check "Plan de Sauvegarde" for historical architectural links to neighboring buildings.

[SOP-TYPE: WATER MAIN BURST]

- Initial Priority: MEDIUM

- Risk Factors: Road erosion, basement flooding, potential structural weakening in old sectors.
- Mandatory Response Protocol:
 1. Contact SEAAL (021 24 24 24) for immediate valve isolation.
 2. Casbah Specific: If the leak is in a low-elevation zone, inspect "Douira" basements for water accumulation.
 3. Coordinate with Police to manage traffic if water volume causes road hazards.

[SOP-TYPE: AGGRESSION / THEFT]

- Initial Priority: HIGH
- Risk Factors: Physical harm, civil unrest, repeat offense in known "hotspots."
- Mandatory Response Protocol:
 1. Dispatch nearest Police Secours (17 / 1548) unit.
 2. Cross-reference incident location with the "Place des Martyrs" or "Alger Centre" CCTV network.
 3. Check historical data for a "Serial Pattern" if similar reports occurred within 2 hours.

[SOP-TYPE: ELECTRICAL / LIGHTING FAILURE]

- Initial Priority: LOW / ROUTINE
- Risk Factors: Reduced public safety at night, increased opportunity for crime.
- Mandatory Response Protocol:
 1. Log for 48-hour maintenance cycle.
 2. Group with existing maintenance tickets in the same Daira to optimize technician routes.
 3. If a whole sector is dark, escalate to MEDIUM and contact Sonelgaz for grid failure check.

Section 3: Historical Pattern Analysis (2020-2025)

- Fire Clusters: Statistics show a 40% increase in electrical fires in *Belouizdad* during July/August due to AC overloads.
- Winter Flooding: *Bab El Oued* drainage systems historically fail when rainfall exceeds 30mm/hour.
- Security Patterns: Increase in petty theft near *Place des Martyrs* during tourist peak hours (10:00 - 14:00).