Question Paper

Exam Date & Time: 21-Nov-2018 (08:30 AM - 11:30 AM)



FIRST SEMESTER B.TECH END SEMESTER EXAMINATIONS, NOV 2018 Basic Mechanical Engineering [MME 1051 - 2018 -PHY]

Marks: 50 Duration: 180 mins.

Α

Answer all the questions.

Instructions to Candidates: Answer ALL questions Missing data may be suitably assumed

Use of Steam Tables is permitted

- Determine the mass of 23.33% wet steam that can be produced by supplying 10031.8 MJ of heat at a pressure of 0.036MPa. The water is fed to the boiler at temperature of 20°C. Also calculate the total enthalpy required by this steam in MJ to reach the dry state. Assume specific heat of water as 4.187kJ/Kg°K.
 - Draw the neat sketch of a Babcock Wilcox boiler and label the parts.
 - C) Briefly explain the function of a Economizer and a Blow Off (2) Valve
- 2) The following gears are available to form a gear train (5)

A)

Gear	Туре	Module	No. of	Numbers
		(mm)	Teeth	available
Α	Helical	3	28	3
В	Bevel	4	38	2
С	Bevel	2	36	2
D	Helical	2	24	1
E	Spur	3	36	1
F	Spur	2	96	1
G	Spur	3	90	2
Н	Bevel	2	40	1
I	Helical	2	32	2
J	Bevel	4	22	1
K	Spur	3	38	2
L	Helical	3	30	2

Design a compound gear train for the maximum possible speed reduction ratio using five shafts and by having helical gear on the driving shaft and bevel gear on the driven shaft. Sketch the arrangement.

- With a neat sketch (two views) explain the working of a stepped cone pulley.
- C) Explain the phenomena of slip and creep in a belt drive. (2)
- With neat sketches and illustrating the pressure volume changes explain the working of a four stroke diesel engine
 - A diesel engine having a cam shaft and operating with a compression ratio of 15:1 has a clearance volume of 200cc. The fuel is being injected at the rate of 24,000 injections per hour. Calculate the indicated power of the engine if the mean effective pressure is 1.6N/mm².
 - C) Briefly explain the properties of an ideal lubricant. (2)
- Explain the need for compounding an impulse turbine and (5) with a neat sketch illustrating the pressure velocity changes explain the working of a pressure velocity compounded impulse turbine.
 - Draw the general layout of a Hydel Power Plant and name (3) the various components?

- C) Briefly explain the functions of an Evaporator and a condenser used in a vapor compression refrigeration system.
- With neat sketches explain taper turning by swiveling the compound rest, counter boring and countersinking operations.
 - Explain any three each properties of moulding sand and pattern making allowances. (3)
 - With a neat sketch explain how arc welding can be carried out using a D.C. power source for thicker workpieces.

----End-----