

Department	Quality Control	Date
Details of Non-Conformity		
NV_CORE: Charging LED is not turn On while device charging.		
Observed By M V R Amar		
Action taken to correct (remedial) non-conformity		
Replaced the Charging LED.		
Root Cause Analysis (main reason)		
Led damaged.		
Corrective Action Taken to avoid the recurrence		
Check the any solder bridges / solder balls / device drops from height.		
Responsibility	M V R Amar	Target Date
Preventive Action Taken to avoid the occurrence		
Maintain proper soldering/ handle the device with care.		
Remarks regarding effectiveness & Sign		
Replaced the Charging LED and Tested.		