


Colour Key:
P&ID Supplied
P&ID Not Supplied



FWH - Powder Area Model



Rev: 1.0 - 13/08/2026
Drawn: TJB

Colour Key:
SiloPack PLC
BulkPack PLC
PACKx PLC
DrySilo PLC
FD Supplied
Phases to Update

P&ID 000556-17 Rework
PwdPRW Phase List:
P01 25kg Tipping
P02 Bulk Tipping
P11 Transport to Silos
P12 Drain Transport Line
E11 Tipping Transport Separator

P&ID 000556-04 P3 Surge Hopper
P3Hop Phase List:
P01 P3 to Silos
P02 P3 Drain Transport Line
P03 P3 Sifter Hopper Sampling
P04 P3 Magnet Cleaning

P&ID 000556-03 P4 Infeed Hopper
P4Hop Phase List:
P01 P4 to Silos
P02 P4 Drain Transport Line
P03 P4 Sifter Hopper Sampling
P04 P4 Magnet Cleaning

P&ID 000556-05 Sifter
Phase List:
Controlled by PwdPRWP11 and E11

P&ID 000556-02 P5 Infeed Hopper
P5Hop Phase List:
P11 P5 Trans A to Silos
P14 P5 Trans A Magnet Cleaning
P21 P5 Trans B to Silos
P24 P5 Trans B Magnet Cleaning

PwdTst Phase List:
P21 P5 Reblend Vac Line Test
P22 P5 Reblend Vac Can Test
P31 P3 Trans Line Test
P32 P3 Trans Vac Can Test
P41 P4 Trans Line Test
P42 P4 Trans Vac Can Test
P51 P5 Trans A Line Test
P52 P5 Trans A Vac Can Test
P53 P5 Trans B Line Test
P54 P5 Trans B Vac Can Test
P61 PreG A Vac Line Test
P62 PreG A Vac Can Test
P71 PreG B Vac Line Test
P72 PreG B Vac Can Test
P81 PreG C Vac Line Test
P82 PreG C Vac Can Test
P91 Bulk A Vac Line Test
P92 Bulk B Vac Line Test
P93 Bulk A Vac Can Test
P94 Bulk B Vac Can Test

P&ID 000556-11 Vacuum Pumps
PwdVac Phase List:
P11 PRWP11 Bip Tip Vac
P12 PRWP11 Backup Vac
P13 PRWP11 Transport Vac
P21 P5RBDP01 Vac
P31 P3HopP01 Transport Vac
P41 P4HopP01 Transport Vac 1
P42 P4HopP01 Transport Vac 2
P51 P5HopP11 Line A1 Vac
P52 P5HopP11 Line A2 Vac
P53 P5HopP21 Line B1 Vac
P54 P5HopP21 Line B2 Vac
P61 PwdPackAP01 Transport Vac
P62 PwdPackAP01 Packing Vac
P63 PwdPackAP01 Bag Pres Vac
P71 PwdPackBP01 Packing Vac 1
P72 PwdPackBP01 Packing Vac 2
P73 PwdPackBP01 Transport Vac 1
P74 PwdPackBP01 Transport Vac 2
P81 PwdPackCP01 Packing Vac 1
P82 PwdPackCP01 Packing Vac 2
P83 PwdPackCP01 Transport Vac 1
P84 PwdPackCP01 Transport Vac 2
P91 PwdBlkAP01 Bulk A Vac
P92 PwdBlkBP01 Bulk B Vac
P93 PwdBlkxP01 Bulk De-aer Vac
P94 PwdPackAP01 Bag Pres Suction
P95 PwdPackBP01 Bag Pres Suction
P96 PwdPackCP01 Bag Pres Suction

P&ID 000556-07 Silos 1 - 4
PwdSx Phase List:
P01 Tipping to Silo x
P0(3-4) P(3-4) to Silo x
P11 Silo x Separator xx
P12 Silo x Separator xx
P21 Silo x to PreG A Pri
P22 Silo x to PreG A Sec
P23 Silo x to PreG B Pri
P24 Silo x to PreG B Sec
P25 Silo x to PreG C Pri
P26 Silo x to PreG C Sec
P27 Silo x to Bulk A & B Pri
P28 Silo x to Bulk A & B Sec
P91 Silo x Fill Maint
P92 Silo x Empty Maint
E01 Silo x

P&ID 000556-14 Silos 7 & 8
PwdSx Phase List:
P01 Tipping to Silo x
P05 P5 to Silo x
P11 Silo x Separator xx
P12 Silo x Separator xx
P21 Silo x to PreG A
P23 Silo x to PreG B
P25 Silo x to PreG C
P27 Silo x to Bulk A & B
P31 Silo x to P5 Reblend
P91 Silo x Fill Maint
P92 Silo x Empty Maint
E01 Silo x

P&ID 000556-06 Silos 5 & 6
PwdSx Phase List:
P05 P5 to Silo x
P11 Silo x Separator xx
P12 Silo x Separator xx
P21 Silo x to PreG A
P23 Silo x to PreG B
P25 Silo x to PreG C
P27 Silo x to Bulk A & B
P91 Silo x Fill Maint
P92 Silo x Empty Maint
E01 Silo x

P&ID 000556-18 25kg Bag Dump
Tipx Phase List:
TipAP01 Bag Tip to PreG A
TipBP01 Bag Tip to PreG B
TIPCP01 Bag Tip to PreG C
(in PwdPckx FDs)

There doesn't seem to be any code for this line.

P&ID 0001160-01 P5 Reblend
P5RBD Phase List:
P01 P5 Reblend
P02 Drain P5 Reblend Line
E11 Reblend Vac Can

P&ID 000556-09 Bulk Line A
PwdBlkA Phase List:
P01 Trans to Bulk A
P02 Bulk A Trans Line
P03 Bulk A Gas Control
P04 Bulk A Manual Empty
P05 Bulk A Silo Empty O/Ride
P11 Bulk A Vac Can 1
P12 Bulk A Vac Can 2
P13 Bulk A Vac Can 3
P14 Bulk A Vac Can 4
P21 Bulk A Weigh Hopper
P22 Bulk A Weigh Hopper Purge
P23 Bulk A Weigh Hopper Topup
P24 Bulk A Weigh Hopper Vent
P91 Bulk A Fill Maint
P92 Bulk A Empty Maint

P&ID 000556-13 Bulk Line B
PwdBlkB Phase List:
P01 Trans to Bulk B
P02 Bulk B Trans Line
P03 Bulk B Gas Control
P04 Bulk B Manual Empty
P05 Bulk B Silo Empty O/Ride
P11 Bulk B Vac Can 1
P12 Bulk B Vac Can 2
P13 Bulk B Vac Can 3
P14 Bulk B Vac Can 4
P21 Bulk B Weigh Hopper
P22 Bulk B Weigh Hopper Purge
P23 Bulk B Weigh Hopper Topup
P24 Bulk B Weigh Hopper Vent
P91 Bulk B Fill Maint
P92 Bulk B Empty Maint

P&ID 000556-16 25kg Line A
PwdPckA Phase List:
P01 Trans to PreG A
P02 Drain PreG A Trans Line
P03 PreG A Gas Control
P04 PreG A Manual Empty
P05 PreG A Silo Empty O/Ride
P11 PreG Vac Can 1
P12 PreG Vac Can 2
P13 PreG Vac Can 3
P14 PreG Vac Can 4
P91 PreG A Fill Maint
P92 PreG A Empty Maint
ASEAL Heat Sealer

P&ID 000556-08 25kg Line B
PwdPckB Phase List:
P01 Trans to PreG B
P02 Drain PreG B Trans Line
P03 PreG B Gas Control
P04 PreG B Manual Empty
P05 PreG B Silo Empty O/Ride
P06 PreG B Magnet Check
P11 PreG Vac Can 1
P12 PreG Vac Can 2
P13 PreG Vac Can 3
P14 PreG Vac Can 4
P91 PreG B Fill Maint
P92 PreG B Empty Maint

P&ID 000556-10 25kg Line C
PwdPckC Phase List:
P01 Trans to PreG C
P02 Drain PreG C Trans Line
P03 PreG C Gas Control
P04 PreG C Manual Empty
P05 PreG C Silo Empty O/Ride
P06 PreG C Magnet Check
P11 PreG Vac Can 1
P12 PreG Vac Can 2
P13 PreG Vac Can 3
P14 PreG Vac Can 4
P91 PreG C Fill Maint
P92 PreG C Empty Maint

P&ID 000556-19 P5 Bulk Conveyors
PwdBlkP Phase List:
P31 Bulk Pack Pallet Destacker
P32 Bulk Pack Infeed Conveyor
P33 Bulk Pack Outfeed Conveyor

P&ID 000556-15 Bulk Bag Filler A & B
Phase List:
Controlled by PwdBlkA & B

P&ID P4EQ5000 25kg Bag Filler

P&ID P5EQU000 25kg Bag Filler

P&ID P5EQX000 25kg Bag Filler