

Rotor/angle deviation at bus 32
3φ-G fault at bus 21, cleared after 0.100s at t=0.300s by tripping line 21--22

