TI/133D Domestic Oil Storage Tank Spillage and Fire Risk Assessment

This record is for safety purposes only. This report is vaild for the day of assessment only.



Customer Details Test			
Name John Doe			
Address	6th Floor, 4 St. Pauls Square Liverpool, L39AG		

Company Details		
Compnay Name Test Contractor		
Company Address	6th Floor, 4 St. Pauls Square Liverpool, L39AG	

Environment Hazard - Part 1	
Tank is in Jersey, Gurnsey or Isle of Man?	Yes
Tank is in Wales and the installation is after 15 th March 2016?	Yes
Tank capacity is in excess of 2500 litres?	Yes
Tank is within 10 meters of controlled water?	Yes
Tank located where spillage could run into an open drain or to a loose manhole cover?	Yes
Tank is within 50 meters of a borehole or spring?	Yes
Tank is over hard ground / surface that could enable spillage to run-off to reach controlled water?	Yes
Tank is located in a position where the vent pipe outlet is not visable from the fill point?	Yes
Tank is supplying heating oil to a building other than a single family dwelling?	Yes
Any other potential hazard individual to the site?	Yes

Environment Hazard - Part 2		
Tank is located in a flood risk area or is exposed to high wind?	Yes	
Is a Tank restraint provided as recommended by the Tank manufacturer?	Yes	

Servicing Record Sign Off						
Issued by	Signed		Print Name	Test Engineer	Date	2019-11-26
Received By	Signed		Print Name	John Doe	Date	2019-11-26

Landlord Details				
Landlord Name	Jane Lords			
Address	6th Floor, 4 St. Pauls Square Liverpool, L39AG			

Engineer Details		
Engineer Name	Test Engineer	
Engineer OFTEC Number	12343823	

Fire Hazard		
Oil tank is located within 1.8 meters of a non-fire rated building or structure (less than 30 minutes)?	Yes	
Oil tank is located within 760mm of a non-fire rated boundary?	Yes	
Oil tank is located within 1.8 meters of a non-fire rated eaves (less than 30 minutes)?	Yes	
Oil tank is located within 1.8 meters of a construction opening in the building (window/door)?	Yes	
Oil tank is located within 1.8 meters of a flue termination?	Yes	
Oil tank is located on a base which does not extend a minimum of 300mm around all sides of the tank?	Yes	
Is fire protection provided?	Yes	

	Defects Identified	Remedial Recommendations
1	Appliance Defect 1	this is the recommendation for Appliance Defect 1
2	Appliance Defect 2	this is the recommendation for Appliance Defect 2
3	Appliance Defect 3	this is the recommendation for Appliance Defect 3
4	Appliance Defect 4	this is the recommendation for Appliance Defect 4
5	Appliance Defect 5	this is the recommendation for Appliance Defect 5