CD/12 Landlord Oil Installation Check

This record is for safety purposes only. This report is vaild for the day of assessment only.

The equipment should not be used unit! the faults are rectified? Yes



Date 2020-01-03

Print John Doe

Name

	,	,	·		,		,						Safe	ty Through Technology	
Customer Details							Landlord Details								
Na	Name John Doe						Landlord	l Name	Jane Lords						
Address 6th Floor, 4 St. Pauls Square Liverpool, L39AG						А	ddress	6th Floor, 4 St. Pauls Square Liverpool, L39AG							
Company Details							Engineer Details								
Compnay Name Test Contractor							Engineer Name Test Engineer								
Company Addr	ompany Address 6th Floor, 4 St. Pauls Square Liverpool, L39AG						Engineer N	OFTEC lumber							
Appliance Details							Test Results								
Locat	Location Kitchen						Smoke No.	2			Draught	65		inWG	
M	Make Test Make			Model	Test Model			0.001		ppm	CO ₂	25.1		%	
Serial Num	Serial Number DN:1234382						Flue Gas	45	0	Pump			Pump 20)2 psi	
	ake OBMake			Burner Model		remp	remp:			Pressure		Vacuuii	/acuum		
Burner T	Burner Type Back Burner			Tank Type	Sealed		Efficiency Nett:	89		%	Efficiency Gross:	85		%	
Flue T	Flue Type CF - Convent Flue		Fuel Type		Gas		Has a T	1/133 \$	Spillage and	Fire Risk A	re Risk Assessment been carried out? Yes				
Appliance Condi	tion Very Good		Landlord's		Yes	Defe	cts Ide	entified		Remedial F	Recomn	nendatio	ns		
Т	10,7000			Appliance?			1 defect 1			this is	the recommen	dation fo	or defect 1	•	
Schedule							2 defect 2 this is the recommendation for defect 2								
Oil Storage				Oil supply comments		3 defect 3 this is the recommendation for defect 3									
Air Supply				Air supply Pass											
Chimney/FLue				chimney comments			4 defect 4			this is	this is the recommendation for defect 4				
Burner				Burner Comments		5 defect 5			this is	this is the recommendation for defect 5					
Safety Controls Pass Comments Pass comments							Servicing Record Sign Off								
Faults									Serv	ricing Re	cora Sign On				
Has a warning label been affixed to the equipment? Yes							Issued by	Sigr	ned	Λ	Print Test	or	Date 20	020-01-03	
Is it strongly recommended that these faults are remedied urgently? Yes									,	`	Name Engine	EI			

Received By

Signed