TI/133D Domestic Oil Storage Tank Spillage and Fire Risk Assessment This record is for safety purposes only. This report is vaild for the day of assessment only.



Customer Details			
Name	John Doe		
Address	6th Floor, 4 St. Pauls Square Liverpool, L39AG		

Company Details			
Compnay Name	Test Contractor		
Company Address	6th Floor, 4 St. Pauls Square Liverpool, L39AG		

Environment Hazard - Part 1	
Tank is in Jersey, Gurnsey or Isle of Man?	Yes
Tank is in Wales and the installation is after 15 th March 2016?	Yes
Tank capacity is in excess of 2500 litres?	Yes
Tank is within 10 meters of controlled water?	Yes
Tank located where spillage could run into an open drain or to a loose manhole cover?	Yes
Tank is within 50 meters of a borehole or spring?	Yes
Tank is over hard ground / surface that could enable spillage to run- off to reach controlled water?	Yes
Tank is located in a position where the vent pipe outlet is not visable from the fill point?	Yes
Tank is supplying heating oil to a building other than a single family dwelling?	Yes
Any other potential hazard individual to the site?	Yes

	Environment Hazard - Part 2
d? Yes	Tank is located in a flood risk area or is exposed to high wind?
nk er?	Is a Tank restraint provided as recommended by the Tank manufacturer?

Servicing Record Sign Off						
Issued by	Signed			Test Engineer	Date	2020-01-03
Received By	Signed		Print Name	IANN I IAA	Date	2020-01-03

Landlord Details			
Landlord Name	Jane Lords		
Address	6th Floor, 4 St. Pauls Square Liverpool, L39AG		

Engineer Details			
Engineer Name	Test Engineer		
Engineer OFTEC Number	12343823		

Fire Hazard	
Oil tank is located within 1.8 meters of a non-fire rated building or structure (less than 30 minutes)?	Yes
Oil tank is located within 760mm of a non-fire rated boundary?	Yes
Oil tank is located within 1.8 meters of a non-fire rated eaves (less than 30 minutes)?	Yes
Oil tank is located within 1.8 meters of a construction opening in the building (window/door)?	Yes
Oil tank is located within 1.8 meters of a flue termination?	Yes
Oil tank is located on a base which does not extend a minimum of 300mm around all sides of the tank?	Yes
Is fire protection provided?	Yes

Defects Identified		Remedial Recommendations	
1	defect 1	this is the recommendation for defect 1	
2	defect 2	this is the recommendation for defect 2	
3	defect 3	this is the recommendation for defect 3	
4	defect 4	this is the recommendation for defect 4	
5	defect 5	this is the recommendation for defect 5	