MODELLING OF 3 PH VOLTAHGE SOURCE INVERTER

Requirements

HLR

- Pole Voltages from the switching functions .
 Phase voltage from Pole voltages using
- required functions.
 3. Three phase voltages and line voltages from
- the phase voltages and line voltages from the phase voltage.

 4. Three phase current by feeding RL lode with an input frequency of 50 HZ.

- 1.Switching functions for the inputs of different frequncy and Aplitudes.
 2. Dc link current from the Switching functions.
- comparing the pole and phase voltages.

Inputs - 3(va,vb,vc)

- Outputs 1.Switching Functions
 2.Pole voltage
 3.Line Voltage

 - 4. Phase Current
 - 5.DC current.

Made by -Darshan Kolavi



