All Stainless Steel Transducer/Transmitter Multimedia Compatibility
High-Performance Silicon Technology
Imperial Model

OF OMEGA®

0-1 to 0-10,000 psi 0-0.07 to 0-690 bar 100 mV, 0 to 5 V, and 4 to 20 mA Outputs

PX309 Series



✓ 1, 2 & 5 psi Low **Pressure Ranges!**

✓ All Stainless Steel Construction

Gage, Absolute, Compound Gage or Vacuum Pressure

Rugged Solid State Design

✓ High Stability, Low Drift

✓ 0.25% Static Accuracy

✓ IP65 Protection Class

We provide a complete range of services—from product inception, through design and prototypes, to manufacturing and testing. Our application engineers work closely with our customers to customize, design or create entirely new **products**. Call us—whether you're an OEM, manufacturer, or end user.









All models shown smaller than actual size.

Rugged, General **Purpose Transducer**

Common Specifications for 100 mV, 0 to 5 Vdc, and 4 to 20 mA Outputs

- ✓ 1, 2 & 5 psi Low **Pressure Ranges!**
- All Stainless Steel Construction
- **✓** Gage or Absolute Pressure
- ✓ Rugged Solid State Design
- ✓ High Stability, Low Drift
- ✓ 0.25% Static Accuracy
- **✓** IP 65 Protection Class

OMEGA's PX309 Series models below 100 psi use a highaccuracy silicon sensor protected by an oil-filled stainless steel diaphragm. Units 100 psi and above use silicon strain gages molecularly bonded to the stainless steel diaphragm.

Common Specifications

Ranges: -15 to 50 psig, 0 to 1000

psia, 100 to 10,000 psig

Accuracy (Combined Linearity, Hysteresis and Repeatability):

±0.25% BSL, max

Minimum Resistance Between Transducer Body and Any Wire:

1M Ω @ 25 Vdc

Calibration: In vertical direction with

fitting down

Pressure Cycles: 10 million, minimum

Pressure Overload: -15 to 50 psig and 0 to 1000 psia: 3 times rated pressure or 20 psi whichever is greater, 100 to 10,000 psig: 2 times rated pressure

Burst Pressure: -15 to 50 psig and 0 to 1000 psia: 4 times rated pressure or 25 psi whichever is greater, 100 to 10,000 psig: 5 times rated pressure

Long Term Stability (1 Year): ±0.25% of FS, typical

Operating Temperature: -40 to 85°C

(-40 to 185°F)

Pressure Port: 1/4-18 MNPT

Pressure Port Material: -15 to 50 psig and 0 to 1000 psia: 316 SS, 100 to 10,000 psig: 17-4 PH SS

Bandwidth: DC to 1 kHz (typical)

MEGA®

CE: Compliant

Shock: 50 g, 11 ms half-sine

Vibration: ±20 g

Response Time: <1 millisecond

Weight:

PX309: 154 g (5.4 oz),

PX319/329/359: 100 g (3.5 oz)

IP Rating: IP65 **RoHS:** Compliant




mV Output Wiring						
Wiring	M12 and Twist Cable mini DIN Lock					
Excitation (+)	Red	Pin 1	Pin A			
Output (+)	White	Pin 3	Pin C			
Output (-)	Green	Pin 4	Pin D			
Excitation (-)	Black	Pin 2	Pin B			
Spare	_	_	Pin E			
Vent	_	_	Pin F			

5 Vdc Output Wiring					
Wiring	M12 and Twist Cable mini DIN Lock				
Excitation (+)	Red	Pin 1	Pin A		
Excitation (-)	Black	Pin 2	Pin B		
Output (+)	White	Pin 3	Pin C		
N/C†	_	Pin 4	Pin D		
Spare	_	_	Pin E		
Vent	_	_	Pin F		

mA Output Wiring				
Twist- Lock	M12 and mini DIN	Wiring		
Pin A	Pin 1	Red	Supply (+)	
Pin B	Pin 2	Black	Supply (-)	
Pin C	Pin 3	_	N/C†	
Pin D	Pin 4	_	N/C [†]	
Pin E	_	_	Spare	
Pin F	_	_	Vent	
		_ _ _ _	N/C [†] N/C [†] Spare	

† N/C: Do not connect any wires to this pin.



How to Order PX309 Series with 100 mV Outputs

100 mV Output 0-1 to 0-10,000 psi 0-70 mbar to 0-690 bar

PX309 Series



100 mV Output Specifications

(In Addition to Common Specifications on page 2)

Setting Accuracy Zero and Span: ±2% FS (±4% FS for 1 and 2 psi)

Supply Voltage:

-15 to 50 psig and 0 to 1000 psia: 10 Vdc, 100 to 10,000 psig: 5 Vdc typical

100 mV Outputs				
Range	Output	Excitation*		
5 to 1000 psia	100 mV	10 Vdc		
1 psig	20 mV	10 Vdc		
2 psig	40 mV	10 Vdc		
5 to 50 psig	100 mV	10 Vdc		
100 to 10,000 psig	100 mV	5 Vdc		
0 to -15 psig	0 to 100 mV	10 Vdc		
-15 to 0 to +15 psig	-100 to 0 to +100 mV	10 Vdc		
-15 to 30/50 psig	0 to 100 mV	10 Vdc		
-15 to 100/150 psig	0 to 100 mV	5 Vdc		

^{*} Ratiometric Excitation Range: 2 to 10 or 1 to 5 Vdc

Input Impedance: 4k to 13k Ω Output Impedance: 4k to 6k Ω

Zero Shift:

-15 to 50 psig and 0 to 1000 psia: $\pm 0.03\%$ °C (0 to 5 psig/psia is $\pm 0.06\%$ °C, 0 to 2 psig is $\pm 0.08\%$ °C, 0 to 1 psig is $\pm 0.1\%$ °C). 100 to 10,000 psig: $\pm 2\%$ over compensated range ref 25°C

Span Shift:

-15 to 50 psig and 0 to 1000 psia: ±0.03%/°C (0 to 5 psig/psia is ±0.04%/°C, 0 to 2 psig is ±0.05%/°C, 0 to 1 psig is ±0.06%/°C). 100 to 10,000 psig: ±2% over compensated range ref 25°C

Compensated Temperature:

-15 to 50 psig and 0 to 1000 psia: 0 to 50°C, 100 to 10,000 psig: 0 to 55°C

Metric Versions of PX309 also available from OMEGA. Please see PXM309 series.



mini DIN

style.

PX319-050GV, mini DIN connector included, shown smaller than actual size.

To Orde	r	- China				
Ra	ange	1 E m Cabla	mini DIN	Turiet Leek	M12	
psi	bar	1.5 m Cable Connection	mini DIN Connection	Twist-Lock Connection	Connection	
Absolute P	Absolute Pressure					
0 to 5	0 to 0.34	PX309-005AV	PX319-005AV	PX329-005AV	PX359-005AV	
0 to 15	0 to 1	PX309-015AV	PX319-015AV	PX329-015AV	PX359-015AV	
0 to 30	0 to 2.1	PX309-030AV	PX319-030AV	PX329-030AV	PX359-030AV	
0 to 50	0 to 3.4	PX309-050AV	PX319-050AV	PX329-050AV	PX359-050AV	
0 to 100	0 to 6.9	PX309-100AV	PX319-100AV	PX329-100AV	PX359-100AV	
0 to 200	0 to 14	PX309-200AV	PX319-200AV	PX329-200AV	PX359-200AV	
0 to 300	0 to 21	PX309-300AV	PX319-300AV	PX329-300AV	PX359-300AV	
0 to 500	0 to 34	PX309-500AV	PX319-500AV	PX320-500AV	PX359-500AV	
0 to 1000	0 to 69	PX309-1KAV	PX319-1KAV	PX329-1KAV	PX359-1KAV	
Gage Press	sure					
0 to 1	0 to 0.07	PX309-001GV	PX319-001GV	PX329-001GV	PX359-001GV	
0 to 2	0 to 0.14	PX309-002GV	PX319-002GV	PX329-002GV	PX359-002GV	
0 to 5	0 to 0.34	PX309-005GV	PX319-005GV	PX329-005GV	PX359-005GV	
0 to 15	0 to 1	PX309-015GV	PX319-015GV	PX329-015GV	PX359-015GV	
0 to 30	0 to 2.1	PX309-030GV	PX319-030GV	PX329-030GV	PX359-030GV	
0 to 50	0 to 3.4	PX309-050GV	PX319-050GV	PX329-050GV	PX359-050GV	
0 to 100	0 to 6.9	PX309-100GV	PX319-100GV	PX329-100GV	PX359-100GV	
0 to 150	0 to 10	PX309-150GV	PX319-150GV	PX329-150GV	PX359-150GV	
0 to 200	0 to 14	PX309-200GV	PX319-200GV	PX329-200GV	PX359-200GV	
0 to 300	0 to 21	PX309-300GV	PX319-300GV	PX329-300GV	PX359-300GV	
0 to 500	0 to 34	PX309-500GV	PX319-500GV	PX329-500GV	PX359-500GV	
0 to 1000	0 to 69	PX309-1KGV	PX319-1KGV	PX329-1KGV	PX359-1KGV	
0 to 2000	0 to 138	PX309-2KGV	PX319-2KGV	PX329-2KGV	PX359-2KGV	
0 to 3000	0 to 207	PX309-3KGV	PX319-3KGV	PX329-3KGV	PX359-3KGV	
0 to 5000	0 to 345	PX309-5KGV	PX319-5KGV	PX329-5KGV	PX359-5KGV	
0 to 7500	0 to 517	PX309-7.5KGV	PX319-7.5KGV	PX329-7.5KGV	PX359-7.5KGV	
0 to 10,000	0 to 690	PX309-10KGV	PX319-10KGV	PX329-10KGV	PX359-10KGV	
Vacuum and Compound Gage Pressure						
-0 to -15	_	PX309-015VV	PX319-015VV	PX329-015VV	PX359-015VV	
-15 to 0 to +15	_	PX309-015CGV	PX319-015CGV	PX329-015CGV	PX359-015CGV	
-15 to 30	-1.03 to 2.1	PX309-V030GV	PX319-V030GV	PX329-V030GV	PX359-V030GV	
-15 to 50	-1.03 to 3.4	PX309-V050GV	PX319-V050GV	PX329-V050GV	PX359-V050GV	
-15 to 100	-1.03 to 6.9	PX309-V100GV	PX319-V100GV	PX329-V100GV	PX359-V100GV	
-15 to 150	-1.03 to 10.3	PX309-V150GV	PX319-V150GV	PX329-V150GV	PX359-V150GV	

Comes complete with 5-point NIST-traceable calibration.

Notes: 1. Units 100 psig and above may be subjected to vacuum on the pressure port without damage. 2. For alternative performance specifications to suit your application, contact Engineering.

Ordering Examples: PX309-100GV, 100 psi gage pressure transducer with 100 mV output at 5 Vdc excitation and 1.5 m cable termination. PX319-015AV, 15 psi absolute pressure transducer with 100 mV output @ 10 Vdc excitation and mini DIN termination.

PX329-3KGV, 3000 psi gage pressure transducer with 100 mV output @ 5 Vdc excitation and twist-lock 6 pin connector termination. Mating connector sold separately, order **PT06V-10-6S**, Consult Sales for OEM pricing.

How to Order PX309 Series with 0 to 5 Vdc Output

PX329-015G5V shown smaller than actual size.



YE OMEGA®

Twist-lock

style.

O to 5 Vdc Output 0-1 to 0-10,000 psi 0-70 mbar to 0-690 bar

PX309 Series



5V Output Specifications

(In Addition to Common Specifications on page 2)
Total Error Band (Includes Linearity, Hyesteresis, Repeatability, Thermal Hysteresis and Thermal Errors, Not Including Zero and Span Setting Accuracy): ±1.0%
(5 psig/psia is ±1.5%, 2 psig is 3.0% and 1 psig is 4.5%)
Supply Voltage: 9 to 30 Vdc, Supply Current < 10 mA

0 to 5 Vdc Outputs				
Range	Output	Excitation*		
5 to 1000 psia	0 to 5 Vdc	9 to 30 Vdc		
1 to 10,000 psig	0 to 5 Vdc	9 to 30 Vdc		
-15 to 30/50/100/ 150 psig	0 to 5 Vdc	9 to 30 Vdc		
0 to -15 psig	0 to 5 Vdc	9 to 30 Vdc		
-15 to 0 to +15 psig	-5 to 0 to +5 Vdc	9 to 30 Vdc		

^{*} Supply Current < 10 mA

Compensated Temperature: -20 to 85°C (≤ 5 psig/psia is 0 to 50°C)

_		Steened			
To Orde	r				
R	ange	1.5 m Cable	mini DIN	Twist-Lock	M12
psi	bar	Connection	Connection	Connection	Connection
Absolute P	ressure				
0 to 5	0 to 0.34	PX309-005A5V	PX319-005A5V	PX329-005A5V	PX359-005A5V
0 to 15	0 to 1	PX309-015A5V	PX319-015A5V	PX329-015A5V	PX359-015A5V
0 to 30	0 to 2.1	PX309-030A5V	PX319-030A5V	PX329-030A5V	PX359-030A5V
0 to 50	0 to 3.4	PX309-050A5V	PX319-050A5V	PX329-050A5V	PX359-050A5V
0 to 100	0 to 6.9	PX309-100A5V	PX319-100A5V	PX329-100A5V	PX359-100A5V
0 to 200	0 to 14	PX309-200A5V	PX319-200A5V	PX329-200A5V	PX359-200A5V
0 to 300	0 to 21	PX309-300A5V	PX319-300A5V	PX329-300A5V	PX359-300A5V
0 to 500	0 to 34	PX309-500A5V	PX319-500A5V	PX320-500A5V	PX359-500A5V
0 to 1000	0 to 69	PX309-1KA5V	PX319-1KA5V	PX329-1KA5V	PX359-1KA5V
Gage Press	sure				
0 to 1	0 to 0.07	PX309-001G5V	PX319-001G5V	PX329-001G5V	PX359-001G5V
0 to 2	0 to 0.14	PX309-002G5V	PX319-002G5V	PX329-002G5V	PX359-002G5V
0 to 5	0 to 0.34	PX309-005G5V	PX319-005G5V	PX329-005G5V	PX359-005G5V
0 to 15	0 to 1	PX309-015G5V	PX319-015G5V	PX329-015G5V	PX359-015G5V
0 to 30	0 to 2.1	PX309-030G5V	PX319-030G5V	PX329-030G5V	PX359-030G5V
0 to 50	0 to 3.4	PX309-050G5V	PX319-050G5V	PX329-050G5V	PX359-050G5V
0 to 100	0 to 6.9	PX309-100G5V	PX319-100G5V	PX329-100G5V	PX359-100G5V
0 to 150	0 to 10	PX309-150G5V	PX319-150G5V	PX329-150G5V	PX359-150G5V
0 to 200	0 to 14	PX309-200G5V	PX319-200G5V	PX329-200G5V	PX359-200G5V
0 to 300	0 to 21	PX309-300G5V	PX319-300G5V	PX329-300G5V	PX359-300G5V
0 to 500	0 to 34	PX309-500G5V	PX319-500G5V	PX329-500G5V	PX359-500G5V
0 to 1000	0 to 69	PX309-1KG5V	PX319-1KG5V	PX329-1KG5V	PX359-1KG5V
0 to 2000	0 to 138	PX309-2KG5V	PX319-2KG5V	PX329-2KG5V	PX359-2KG5V
0 to 3000	0 to 207	PX309-3KG5V	PX319-3KG5V	PX329-3KG5V	PX359-3KG5V
0 to 5000	0 to 345	PX309-5KG5V	PX319-5KG5V	PX329-5KG5V	PX359-5KG5V
0 to 7500	0 to 517	PX309-7.5KG5V	PX319-7.5KG5V	PX329-7.5KG5V	PX359-7.5KG5V
0 to 10,000	0 to 690	PX309-10KG5V	PX319-10KG5V	PX329-10KG5V	PX359-10KG5V
Vacuum and Compound Gage Pressure					
0 to -15		PX309-015V5V	PX319-015V5V	PX329-015V5V	PX359-015V5V
-15 to 0 to +15	_	PX309-015CG5V	PX319-015CG5V	PX329-015CG5V	PX359-015CG5V
-15 to 30	-1.03 to 2.1	PX309-V030G5V	PX319-V030G5V	PX329-V030G5V	PX359-V030G5V
-15 to 50	-1.03 to 3.4	PX309-V050G5V	PX319-V050G5V	PX329-V050G5V	PX359-V050G5V
-15 to 100	-1.03 to 6.9	PX309-V100G5V	PX319-V100G5V	PX329-V100G5V	PX359-V100G5V
-15 to 150	-1.03 to 10.3	PX309-V150G5V	PX319-V150G5V	PX329-V150G5V	PX359-V150G5V

Comes complete with 5-point NIST-traceable calibration.

Ordering Examples: PX309-100G5V, 100 psi gage pressure transducer with 0 to 5 Vdc output and 1.5 m cable termination.

PX319-015A5V, 15 psi absolute pressure transducer with 0 to 5 Vdc output and mini DIN termination. **PX329-3KG5V**, 3000 psi gage pressure transducer with 0 to 5 Vdc output and twist-lock 6 pin connector termination. Mating connector sold separately; order **PT06V-10-6S**. Consult Sales for OEM pricing.

Metric Versions of PX309 also available from OMEGA. Please see PXM309 series.

^{*}Notes: 1. Units 100 psig and above may be subjected to vacuum on the pressure port without damage. 2. For alternative performance specifications to suit your application, contact Engineering.

How to Order PX309 Series with 4 to 20 mA Output

CE OMEGA®

PX309-030GI shown smaller than actual size.



4 to 20 mA Output 0-1 to 0-10,000 psi 0-70 mbar to 0-690 bar

PX309 Series



4 to 20 mA Output Specifications (In Addition to Commo

(In Addition to Common Specifications on page 2) Total Error Band (Includes Linearity, Hyesteresis, Repeatability, Thermal Hysteresis and Thermal Errors, Not Including Zero and Span Setting Accuracy): ±1.0% (5 psig/psia is ±1.5%, 2 psig is 3.0% and 1 psig is 4.5%) Supply Voltage: 9 to 30 Vdc

4 to 20 mA Outputs			
Range Output Excitation			
All models (psia, psig)	4 to 20 mA	9 to 30 Vdc	
-15 to 0 to +15 psig	4 to 12 to 20 mA	9 to 30 Vdc	

Compensated Temperature: -20 to 85°C (≤ 5 psig/psia is 0 to 50°C)

Reverse Polarity Protected Over Voltage Protection

			The state of the s		
To Order	To Order				
Ra	nge	4.5 Oakla	ii DIN	Todak Laula	1440
psi	bar	1.5 m Cable Connection	mini DIN Connection	Twist-Lock Connection	M12 Connection
Absolute Pre	essure				
0 to 5	0 to 0.34	PX309-005AI	PX319-005AI	PX329-005AI	PX359-005AI
0 to 15	0 to 1	PX309-015AI	PX319-015AI	PX329-015AI	PX359-015AI
0 to 30	0 to 2.1	PX309-030AI	PX319-030AI	PX329-030AI	PX359-030AI
0 to 50	0 to 3.4	PX309-050AI	PX319-050AI	PX329-050AI	PX359-050AI
0 to 100	0 to 6.9	PX309-100AI	PX319-100AI	PX329-100AI	PX359-100AI
0 to 200	0 to 14	PX309-200AI	PX319-200AI	PX329-200AI	PX359-200AI
0 to 300	0 to 21	PX309-300AI	PX319-300AI	PX329-300AI	PX359-300AI
0 to 500	0 to 34	PX309-500AI	PX319-500AI	PX320-500AI	PX359-500AI
0 to 1000	0 to 69	PX309-1KAI	PX319-1KAI	PX329-1KAI	PX359-1KAI
Gage Pressu	re				
0 to 1	0 to 0.07	PX309-001GI	PX319-001GI	PX329-001GI	PX359-001GI
0 to 2	0 to 0.14	PX309-002GI	PX319-002GI	PX329-002GI	PX359-002GI
0 to 5	0 to 0.34	PX309-005GI	PX319-005GI	PX329-005GI	PX359-005GI
0 to 15	0 to 1	PX309-015GI	PX319-015GI	PX329-015GI	PX359-015GI
0 to 30	0 to 2.1	PX309-030GI	PX319-030GI	PX329-030GI	PX359-030GI
0 to 50	0 to 3.4	PX309-050GI	PX319-050GI	PX329-050GI	PX359-050GI
0 to 100	0 to 6.9	PX309-100GI	PX319-100GI	PX329-100GI	PX359-100GI
0 to 150	0 to 10	PX309-150GI	PX319-150GI	PX329-150GI	PX359-150GI
0 to 200	0 to 14	PX309-200GI	PX319-200GI	PX329-200GI	PX359-200GI
0 to 300	0 to 21	PX309-300GI	PX319-300GI	PX329-300GI	PX359-300GI
0 to 500	0 to 34	PX309-500GI	PX319-500GI	PX329-500GI	PX359-500GI
0 to 1000	0 to 69	PX309-1KGI	PX319-1KGI	PX329-1KGI	PX359-1KGI
0 to 2000	0 to 138	PX309-2KGI	PX319-2KGI	PX329-2KGI	PX359-2KGI
0 to 3000	0 to 207	PX309-3KGI	PX319-3KGI	PX329-3KGI	PX359-3KGI
0 to 5000	0 to 345	PX309-5KGI	PX319-5KGI	PX329-5KGI	PX359-5KGI
0 to 7500	0 to 517	PX309-7.5KGI	PX319-7.5KGI	PX329-7.5KGI	PX359-7.5KGI
0 to 10,000	0 to 690	PX309-10KGI	PX319-10KGI	PX329-10KGI	PX359-10KGI
Vacuum and	Vacuum and Compound Gage Pressure				
0 to -15	_	PX309-015VI	PX319-015VI	PX329-015VI	PX359-015VI
-15 to 0 to +15	_	PX309-015CGI	PX319-015CGI	PX329-015CGI	PX359-015CGI
-15 to 30	-1.03 to 2.1	PX309-V030GI	PX319-V030GI	PX329-V030GI	PX359-V030GI
-15 to 50	-1.03 to 3.4	PX309-V050GI	PX319-V050GI	PX329-V050GI	PX359-V050GI
-15 to 100	-1.03 to 6.9	PX309-V100GI	PX319-V100GI	PX329-V100GI	PX359-V100GI
-15 to 150	-1.03 to 10.3	PX309-V150GI	PX319-V150GI	PX329-V150GI	PX359-V150GI

Comes complete with 5-point NIST-traceable calibration.

PT06V-10-6S. Consult Sales for OEM pricing.

Notes: 1. Units 100 psig and above may be subjected to vacuum on the pressure port without damage. 2. For alternative performance specifications to suit your application, contact Engineering.

Ordering Examples: PX309-100GI, 100 psi gage pressure transducer with 4 to 20 mA output and 1.5 m cable termination. PX319-015AI, 15 psi absolute pressure transducer with 4 to 20 mA output and mini DIN termination. PX329-3KGI, 3000 psi gage pressure transducer with 4 to 20 mA output and twist-lock 6 pin connector termination. Mating connector sold separately; order

Metric Versions of PX309 also available from OMEGA. Please see PXM309 series.


PX309 Series Accessories





DP8PT, shown smaller than actual size.





Accessories

Model No.	Description
CAL-3	Recalibration with 5 point NIST traceable documentation
PT06V-10-6S	Mating connector for PX329
CA-329-4PC24-005	4-conductor mating twist-lock 6 pin connector with 1.5 m (5') cable for PX329
CX5302	Extra mini DIN connector for PX319
CA-359-4PC22-2M	2 m (6') vented cable with M12 connector for PX359 for gage ranges <100 psi
CA-359-4PC22-5M	5 m (16') vented cable with M12 connector for PX359 for gage ranges <100 psi
M12C-PVC-4-S-F-5	5 m (16') PVC cable, straight 4-pin M12 female connector one end, flying leads one end, for all PX359 absolute ranges and gage ranges >100 psi
DP8PT	4-digit meter for both mV/V and amplified PX3*9 models
DP25B-S	4-digit strain meter for mV/V PX3*9 models
DP25B-E	4-digit process meter for amplified PX3*9 models

Note: Complete meter specifications can be found at OMEGA.

Installation Notes





On the PX3*9 Series 0 to 5 Vdc output, do not short the Output(+) to Excitation(+) as permanent damage to the electronics will occur.



All models shown smaller than actual size.

PX309-100GV.



Installation Notes

PX309 Series

All PX309 (gage and absolute) use a vented cable. Gage PX309 sensors up to 100 PSIG must be terminated in a clean dry area that is open to atmosphere for correct operation. All other sensors (> 100 psig and all psia ranges) must be terminated in a dry area but do not need to be vented to atmosphere. These cables should be sealed (e.g. RTV) to protect the sensor from moisture getting in to the sensor through the cable.

PX319 Series

All PX319 are vented through a hole in the connector and through the mating connector. A vented cable must be used for low pressure gage sensors up to 100 PSIG and must be terminated in a clean dry area that is open to atmosphere for correct operation. The gasket for the DIN mating connector has a special stiffener (included) between the mating surfaces and is used to maintain the IP65 rating (Spare Gaskets are Part number P002612). See vented cable assembly CA-319-4PC24-XXX-WP for gage pressure under 100 psi. All other PX319 sensors can use standard cable but must be terminated in a dry location or sealed to prevent water from getting into the cable/ sensor. See cable assembly CA-319-4PC24-XXX for all other pressure ranges.

PX329 Series

All PX329 are vented through Pin F of the twist-lock connector. Gage PX329 up to 100 PSIG must be vented for correct operation and must use the connector PT06V-10-6S which has no socket on pin F. Cables for these sensors must use a vented cable, be sealed at the back of the mating connector and be terminated in a dry clean area open to the atmosphere. See cable assembly CA-329-4PC24-XXX-WP for gage pressure under 100 psi. All other PX329 can use a the standard PT06F10-6S connector or cables (See cable assembly CA-329-4PC24-XXX).

PX359 Series

All PX359 are vented through a hole in the connector. Gage PX359 up to 100 psig must be vented for correct operation and must use the either the CA-359-4PC22-2M or CA-359-4PC22-5M or similar cable. They also must be terminated in a clean dry area open to the atmosphere. All other PX359 can use a standard M12 mating cable like the M12C-PVC-4-S-F-5.