

Timed turns
Linear fit
Fit ±1σ
Settings of the photos
ω (rad s⁻¹)
Motor setting S
0.0
0.5
1.0
1.5
2.0
0
20
40
60
80