
The decisive architectural change
One client radio
293.9
Two AP paths
3.1
10^0
10^1
10^2
Main-condition misses / M


Other levers affect the margin
Full dual-radio
3.1
No online learning
3.6
No power control
3.6
No cadence timing
3.1
No adaptive video
3.1
Add scheduled control
3.1
0
1
2
3
4
5
Misses / M