EL AL FLIGHT DECK - ZEROTECH CHECKLIST

PRE FLIGHT FLOWS

Open the airport and route charts.
Check forecasts at https://metar-taf.com for choosing the Runway being used.

>> START SKYTRACK <<

TAKEOFF THE PLANE
LAND IT BACK
TAXI TO THE GATE

PRE START CHECKLIST

ANCHOR .....ON
BATTERY .....ON
NAV LIGHTS .....ON
LOGO LIGHT .....AS REQUIRED

2 Minutes Prior GPU Release/Before Boarding

FUEL PUMPS .....ON
APU .....ON
APU BLEED .....ON
PACKS .....ON

PUSH AND START CHECKLIST

BEACON LIGHT .....ON
PACKS .....OFF

Request Pushback & Startup Clearance

ANCHOR .....OFF

Initiate Pushback

ENGINE 1 .....START
ENGINE 1 .....ON
ENGINE 2 .....START
ENGINE 2 .....ON

BEFORE TAXI CHECKLIST

PACKS .....ON
APU BLEED .....OFF
APU .....OFF
FLAPS .....FLAPS 1

Request Taxi Clearance

TAXI CHECKLIST

TAXI LIGHTS .....ON
WIPERS .....AS REQUIRED
TAXI to assigned runway .....SPEED Max. 35 knots

BEFORE TAKE-OFF CHECKLIST

LANDING LIGHTS .....ON
LANDING ALT LIGHTS .....ON
STROBE LIGHT .....ON
TAXI LIGHTS .....OFF
LANDING LIGHTS .....ON
STROBE LIGHT .....ON

Request Takeoff Clearance

>> V1 - 160 <<

>> VR - 162 <<

>> VR - 162 <<

TAKE-OFF & AFTER TAKEOFF CHECKLIST

Smoothly increase thrust to 40% to let engine spool up

TAKEOFF THRUST .....FULL
POSITIVE RATE OF CLIMB .....GEAR UP

Passing 600 ft

FLAPS .....RETRACT

CLIMB-OUT CHECKLIST

BELOW 2'000FT .....MAX 250 KTS

Passing 2'000 ft

LANDING LIGHTS .....OFF
LANDING ALT LIGHTS .....OFF

CRUISE & DESCENT PREPERATION

Reaching 0 kts On Pad

ANCHOR .....ON

Before Decent

CURRENT RWY IN USE .....CHECK

Decent

ANCHOR .....OFF
THROTTLE.....GRAD INC BY 10% UNTIL POS RATE

Below 2'000 ft

WIPERS .....AS REQUIRED
SPEED.....MAX 250 KTS
LANDING LIGHTS .....ON
LANDING ALT LIGHTS .....ON

APPROACH CHECKLIST

LANDING LIGHTS .....CHECK ON
LANDING ALT LIGHTS .....CHECK ON
SPEED: .....ESTABLISH 165 KTS
LANDING LIGHTS .....CHECK ON
LANDING ALT LIGHTS .....CHECK ON
FLAPS .....FLAPS 1
SPEED: .....ESTABLISH 200 KTS
FLAPS .....FLAPS 2
SPEED: .....ESTABLISH 190 KTS

On Final Approach

SPEED: .....ESTABLISH 180 KTS
LANDING GEAR .....DOWN
LANDING GEAR GREEN .....FLAPS 3

Final Descent

FLAPS .....FLAPS 4
SPEED: .....ESTABLISH 170 KIAS

LANDING CHECKLIST

LANDING GEAR .....CHECK DOWN

After Touch-Down

REV THR + SPOILERS .....ENGAGE
AT 60 KTS .....REV THR+ SPOILERS OFF

AFTER LANDING CHECKLIST

FLAPS .....RETRACT
LANDING LIGHTS .....OFF
LANDING ALT LIGHTS .....OFF
STROBE LIGHTS .....OFF
TAXI LIGHTS .....ON
LOGO LIGHTS LIGHTS .....AS REQUIRED
APU .....ON

Taxi to Assigned Gate/Parking (Speed Max 30 knots)

APU BLEED .....ON

Turning Into The Gate:

TAXI LIGHTS .....OFF

PARKING / SHUTDOWN CHECKLIST

ANCHOR .....ON
ENGINE 1 .....OFF
ENGINE 2 .....OFF
BEACON LIGHTS .....OFF
NAV LIGHTS .....OFF
GROUND CONTACT .....ESTABLISH

>> SKYTRACK – PIREP FILED ! <<

BEFORE TAKE-OFF CHECKLIST

PACKS .....OFF
APU BLEED .....OFF
APU .....OFF
FUEL PUMPS .....OFF
LOGO LIGHTS .....OFF
BATTERY .....OFF