3D printing

- Gears
 - o 16 teeth
 - o 8 teeth
- Boxes x3
- Magnet fastener
 - o x12 left
 - o x12 right
- Button's block
 - \circ bottom
 - o upper
- Turntable stand
- Nut fastener

Laser cutting

- Niryo stand x2
- centre
- Turntable stand
- T block
 - o x4
- Turntable
 - o bottom
 - o upper
- Boxes stand