Quick Capture V1.0

Overview

The Quick Capture Macro for Solidworks is written in VBA and is intended a one-click method for quickly exporting a jpeg capture of the current view.

Revisions

Version	Released	Author	Notes
V1.0	05/02/2022	DB	Initial Issue


Installation

Download the latest .ZIP folder and unzip.


Assign the macro to the Solidworks tool bar. For help assigning the macro to a tool bar button follow these steps.

User guide

Run the macro by clicking the macro button on the tool bar. See above steps on how to assign a macro button.



A JPEG of the current viewpoint will be exported to the active document's directory. The exported image will take the same name as the active document followed by '_Capture_(0)'. Any subsequent exports shall be named incrementally.



If the macro runs on an active document which has never been saved, the image shall not be exported, and the following message displayed.

