
Inspection
tIIn
pIRoom
tIRoom
30
pISpace
tIInRepair
pIStart
tIStart
pIGauge
tIGauge_1
tIGauge_2
tIGauge_3
tIGauge_4
tIGauge_5
pIClean
tIClean_1
tIClean_2
tIClean_3
tIClean_4
tIClean_5
tIClean_6
tIClean_7
tICleanSkip
pINDT
tINDT_1
tINDT_2
tINDT_3
tINDT_4
tINDT_5
tINDTSkip
pIThreads
tIThreads_1
tIThreads_2
pIMeasure
tIMeasure_1
tIMeasure_2
tIMeasure_3
tIMeasure_4
tIMeasure_5
pIUT
tIUT_1
tIUTSkip
pIFinish
tIFinish_1
tIFinish_2
tIFinish_3
tIFinish_4
tIFinish_5
tIFinish_6
tIFinish_7
pIMark
tIMark_1
tIMark_2
tIMark_3
tIMark_4
tIMark_5
tIMarkSkip
pIReport
tIReport_1
tIReport_2
pIDone
tIOk
tIMach
tIHb
tIScrap