PROFIT ANALYSIS BY INVOICE DETAILS

#	PART NO	DESCRIPTION	War/ FS	I = Part S = Labor	QTY	TOTAL	COST	N. MARGIN	%
INVOICE									
1	HBPSI2608001	RT6630 EDARAN RIZ SDN BHD							
	SB-HNMG1401005P-FR	HINO VICTOR 500 LOWER CAP SIDE BUMPER RH	NONE	I	1.00	99.60	60.00	39.60	39.76 %
	CP-HNMG1401008FR	HINO VICTOR 500 CORNER PANEL RH	NONE	I	1.00	1,831.68	100.00	1,731.68	94.54 %
	LG-HNMG1402011PFR	HINO VICTOR 500 LIGHT PROTECTOR COVER RH	NONE	I	1.00	49.80	30.00	19.80	39.76 %
	81110-EW051	HEADLAMP ASSY, RH	NONE	I	1.00	1,616.28	1,519.06	97.22	6.02 %
		FRONT BUMPER BAR	NONE	I	1.00	983.46		983.46	100.00 %
		FRONT BUMPER EXTENSION RH	NONE	I	1.00	929.00		929.00	100.00 %
		LAMP ASSY, FR TURN SIGNAL, RH	NONE	I	1.00	157.69		157.69	100.00 %
		PAINTING MATERIALS	NONE	I	1.00	190.00		190.00	100.00 %
		LABOUR FEE	NONE	S	1.00	1,197.00		1,197.00	100.00 %
					9.00	7,054.51	1,709.06	5,345.45	75.77 %
2	HBPSI2608002	VPN1847 EDARAN RIZ SDN BHD							
	44640-2200C	AIR MASTER ASSY	NONE	I	1.00	630.80	380.00	250.80	39.76 %
	AT-A260-HDN	AOTO A260 HARDENER 250ML-C/W EFF	NONE	I	3.00				0.00 %
	CST-3L	CS THINNER 3L/2.5KG (GP SOLVENT)	NONE	I	1.00		31.50	-31.50	0.00 %
	3440-ANCHOR	15MM X 40M ANCHOR M509 MASKING TAPE	NONE	I	5.00		19.20	-19.20	0.00 %
	240-ANCHOR	47MM X 40M ANCHOR M509 MASKING TAPE	NONE	I	2.00		23.16	-23.16	0.00 %
	WS-10178-1L	WS 10178 2K M/BLACK 1L	NONE	I	1.00		35.00	-35.00	0.00 %
	UPOL-EXTRA	880ML - UPOL EXTRA GOLD FINE POLYESTER FILLER	NONE	I	1.00		75.00	-75.00	0.00 %
	WS-2KT-3L	WS 2K THINNER 3L/2.5KG	NONE	I	1.00		53.33	-53.33	0.00 %
	LG-HIC8-X XZU38-ST LH	FRT LMT GLASS (XYG)	NONE	I	1.00	609.81	355.00	254.81	41.79 %
	AT-SE-1	AOTO SPECIAL EFFECT - A1728 / 058	NONE	I	3.00		270.00	-270.00	0.00 %
	TSFC-XZU605	XZU605 FRONT CABIN	NONE	I	1.00	50,930.91	13,666.67	37,264.24	73.17 %
	IKIIT-HN-CONDENSER	HINO - CONDENSER	NONE	I	1.00	315.40	190.00	125.40	39.76 %
	K-HNWU640	HINO DUTRO WU640 KANGAROO BAR	NONE	I	1.00	415.00	245.00	170.00	40.96 %
	M0A-HNXZU640FL	XZU640 MIRROR ARM LH	NONE	I	1.00	199.20	120.00	79.20	39.76 %
	SL1605FL	XZU720 DOUBLE GLASS SIDE MIRROR LH	NONE	I	1.00	149.40	92.50	56.90	38.09 %
	SL1605FR	XZU720 DOUBLE GLASS SIDE MIRROR RH	NONE	I	1.00	149.40	92.50	56.90	38.09 %
	CP-HNDUXZU-FL	XZU640 CORNER PANEL LH	NONE	I	1.00	107.90	65.00	42.90	39.76 %
	CP-HNDUXZU-FR	XZU640 CORNER PANEL RH	NONE	I	1.00	107.90	65.00	42.90	39.76 %
	302-HN650-FL	XZU640 STAND PANEL LH	NONE	I	1.00	141.10	85.00	56.10	39.76 %
	205/85R16	BRIDGESTONE 205/85R16-R205	NONE	I	2.00	1,660.00	975.00	685.00	41.27 %
	K2-BATTERY	BATTERY	NONE	I	2.00	896.40	540.00	356.40	39.76 %
	KTE-DST-2-0002	COMPANY STICKER	NONE	I	1.00	80.00	80.00		0.00 %
	KTE-DST-2-0004	BTM / BDM STICKER	NONE	I	1.00	80.00	25.00	55.00	68.75 %
	KTE-NP-SS-0015	SQUARE TYRE NUMBER PLATE - STEEL	NONE	I	1.00	74.70	45.00	29.70	39.76 %
	75311-37320	PLATE, FR NAME, NO.1 (STICKER HINO)	NONE	I	1.00	168.91	111.13	57.78	34.21 %
	75311-37330	PLATE, FRONT NAME, NO.1 (300)	NONE	I	1.00	166.63	109.63	57.00	34.21 %
	FCAA-ANTENNA	ANTENNA	NONE	I	1.00	49.80	30.00	19.80	39.76 %
	PF-STICKER-3MX2	STICKER - 3M X 2" (RED & YELLOW)	NONE	I	6.00	79.68	48.00	31.68	39.76 %
	205/85R16	BRIDGESTONE 205/85R16-R205	NONE	I	1.00	830.00	487.50	342.50	41.27 %
		COVER SUB-ASSY, FRONT PANEL	NONE	I	1.00	1,182.75		1,182.75	100.00 %
		WINDSHIELD WEATHER-STRIP	NONE	I	1.00	215.08		215.08	100.00 %
		WHEEL CAP (LH FRONT)	NONE	I	1.00	180.69		180.69	100.00 %
		COVER, FRONT DOOR FRONT LOWER FRAME, UPPER LH	NONE	I	1.00	194.09		194.09	100.00 %
		WEATHERSTRIP, FRONT DOOR, LH	NONE	I	1.00	106.92		106.92	100.00 %
		WEATHERSTRIP, FRONT DOOR, NO.2 LH	NONE	I	1.00	94.43		94.43	100.00 %
		WEATHERSTRIP ASSY, FRONT DOOR GLASS, OUTER LH	NONE	I	1.00	91.86		91.86	100.00 %

#	PART NO	DESCRIPTION	War/ FS	I = Part S = Labor	QTY	TOTAL	COST	N. MARGIN	%
		REFLEX SIDE REFLECTOR ASSEMBLY LH	NONE	I	1.00	201.59		201.59	100.00 %
		LAMP ASSY, SIDE TURN SIGNAL, LH	NONE	I	1.00	357.30		357.30	100.00 %
		STAY SUB-ASSY, OUTER REAR VIEW MIRROR, LH	NONE	I	1.00	1,103.04		1,103.04	100.00 %
		OUTER MIRROR COVER LH	NONE	I	1.00	304.00		304.00	100.00 %
		GARNISH, FRONT PILLAR, LH	NONE	I	1.00	192.66		192.66	100.00 %
		INSTRUMENT PANEL SPEAKER PANEL SUB-ASSEMBLY NO.2	NONE	I	1.00	108.97		108.97	100.00 %
		GARNISH, RADIATOR GRILLE, NO.3	NONE	I	1.00	172.81		172.81	100.00 %
		ORNAMENT, RADIATOR GRILLE (OR FRONT PANEL)	NONE	I	1.00	283.86		283.86	100.00 %
		PLATE, FRONT DOOR NAME, RH	NONE	I	1.00	226.39		226.39	100.00 %
		PLATE, FRONT DOOR NAME, LH	NONE	I	1.00	226.86		226.86	100.00 %
		GLASS SUB-ASSY, FRONT DOOR, LH	NONE	I	1.00	168.82		168.82	100.00 %
		XZU640 STICKER	NONE	I	1.00	31.63		31.63	100.00 %
		REAR CABIN FONT CORNER CAP LH	NONE	I	1.00	800.00		800.00	100.00 %
		REAR CABIN SIDE DOOR HINGE LH	NONE	I	1.00	550.00		550.00	100.00 %
		PAINTING MATERIALS	NONE	I	1.00	377.59		377.59	100.00 %
		MISCELLANEOUS ITEMS	NONE	I	1.00	114.00		114.00	100.00 %
		LABOUR FEE	NONE	S	1.00	16,017.00		16,017.00	100.00 %
					69.00	81,145.28	18,315.12	62,830.16	77.43 %
3	HBPSI2608003	VMH8922 EDARAN RIZ SDN BHD							
	CP-HNDUXZU-FL	XZU640 CORNER PANEL LH	NONE	I	1.00	1,692.81	65.00	1,627.81	96.16 %
	CP-HNDUXZU-FR	XZU640 CORNER PANEL RH	NONE	I	1.00	1,692.81	65.00	1,627.81	96.16 %
	205/85R16	YOKOHAMA 205/85R16 - 12PLY - LT151	NONE	I	1.00	747.00	500.00	247.00	33.07 %
	AT-SE-1	AOTO SPECIAL EFFECT - A1728PU	NONE	I	3.00		270.00	-270.00	0.00 %
	AT-A260-HDN	AOTO A260 HARDENER 250ML-C/W EFF	NONE	I	3.00				0.00 %
	240-ANCHOR	47MM X 40M ANCHOR M509 MASKING TAPE	NONE	I	4.00		46.80	-46.80	0.00 %
	3460-ANCHOR	15MM X 60M ANCHOR M509 MASKING TAPE	NONE	I	8.00		45.60	-45.60	0.00 %
	UPOL-EXTRA	880ML - UPOL EXTRA GOLD FINE POLYESTER FILLER	NONE	I	1.00		75.00	-75.00	0.00 %
	WS-2KT-3L	WS 2K THINNER 3L/2.5KG	NONE	I	1.00		55.00	-55.00	0.00 %
	CST-3L	CS THINNER 3L/2.5KG (GP SOLVENT)	NONE	I	2.00		64.00	-64.00	0.00 %
	WS-10178-1L	WS 10178 2K M/BLACK 1L	NONE	I	1.00		35.00	-35.00	0.00 %
	TSFC-XZU605	XZU605 FRONT CABIN	NONE	I	1.00	65,614.16	13,500.00	52,114.16	79.43 %
	NEXA-396-5L	NEXA AUTO P396 - LINE 5L - 10089	NONE	I	2.00		406.00	-406.00	0.00 %
	M0A-HNXZU640FL	XZU640 MIRROR ARM LH	NONE	I	1.00	199.20	120.00	79.20	39.76 %
	M0A-HNXZU640FR	XZU640 MIRROR ARM RH	NONE	I	1.00	199.20	120.00	79.20	39.76 %
	SL1605FL	XZU720 DOUBLE GLASS SIDE MIRROR LH	NONE	I	1.00	157.70	90.00	67.70	42.93 %
	SL1605FR	XZU720 DOUBLE GLASS SIDE MIRROR RH	NONE	I	1.00	157.70	90.00	67.70	42.93 %
	K-HNWU640	HINO DUTRO WU640 KANGAROO BAR	NONE	I	1.00	398.40	250.00	148.40	37.25 %
	LG-HIC8-X XZU38-ST LH	FRT LMT GLASS (XYG)	NONE	I	1.00	609.81	355.00	254.81	41.79 %
	K2-AR-24V	ALTERNATOR REGULATOR 24V	NONE	I	1.00	265.60	160.00	105.60	39.76 %
	KTE-DST-2-0002	COMPANY STICKER	NONE	I	1.00	132.80	80.00	52.80	39.76 %
	KTE-DST-2-0004	BTM / BDM STICKER	NONE	I	1.00	41.50	25.00	16.50	39.76 %
	KTE-NP-SS-0015	SQUARE TYRE NUMBER PLATE - STEEL	NONE	I	1.00	74.70	45.00	29.70	39.76 %
	PF-LED-24V-2 R	LED LAMP 24V-2" ROUND	NONE	I	4.00	66.40	40.00	26.40	39.76 %
	16711-78280	FAN SHROUD	NONE	I	1.00	658.80	411.75	247.05	37.50 %
	PF-STICKER-3MX2	STICKER - 3M X 2" (RED & YELLOW)	NONE	I	6.00	79.68	48.00	31.68	39.76 %
		HEADLAMP ASSY, RH	NONE	I	1.00	527.75		527.75	100.00 %
		REFLEX SIDE REFLECTOR ASSEMBLY LH	NONE	I	1.00	91.59		91.59	100.00 %
		STEP PLATE LH	NONE	I	1.00	171.14		171.14	100.00 %
		WINDSHIELD WEATHERSTRIP	NONE	I	1.00	215.08		215.08	100.00 %
		PAINTING MATERIALS	NONE	I	1.00	380.00		380.00	100.00 %
		MISCELLANEOUS ITEMS	NONE	I	1.00	90.25		90.25	100.00 %
		LABOUR FEE	NONE	S	1.00	2,838.60		2,838.60	100.00 %
					57.00	77,102.68	16,962.15	60,140.53	78.00 %
					135.00	165,302.47	36,986.33	128,316.14	77.63 %

#	PART NO	DESCRIPTION	War/ FS	I = Part S = Labor	QTY	TOTAL	COST	N. MARGIN	%
					165,302.47	165,302.47	36,986.33	128,316.14	77.63%