

Roof Analysis Report

Report: istockphoto-2032788923-2048x2048.webp

Generated: September 18, 2025

Property: 123 example street

Client: john smith

Inspection Date: September 18, 2025



Damage Overview

Missing Shingles: A large area of shingles is missing from the roof surface, exposing the underlying sheathing. This leaves the roof vulnerable to water ingress and further damage. **Severity:** High.

Recommendation: Replace all missing shingles with new, matching shingles to restore the roof's integrity. Ensure proper underlayment is installed or repaired before replacing shingles. **Location:** Center quadrant.

Recommendations

Recommendations

Contact a qualified roofing contractor for a thorough inspection and repair quote.

Take temporary measures to protect the exposed area, such as covering it with a tarp if safe to do so.

Monitor the area for any signs of leaks or further damage.

Cost Estimates

Estimated Cost Range: Missing Shingles: £600–£1,200 Note: These are estimated costs only.

Actual pricing may vary depending on location, contractor rates, and material availability.

Disclaimer: This AI analysis must be verified by a certified professional. Cost estimates are approximate.