


Noticed that some changes in pedestals exist for the same channel across all GEMs and APVs
Potential cause: noise in electronics?



GEM



APV




Channel




Pedestals for GEM 2, APV 7, Channel 2 by Run Number


Noticed that some changes in pedestals exist for the same channel across all GEMs and APVs
Potential cause: noise in electronics?



GEM



APV



Channel



Pedestal changes for all channels of the same number caused by electronic noise?

Other notes:

- Last week at TRIUMF (working on documentation)
- Potential new hit detection method: Gaussian fit in time as filter – [source](#)
 - Runs at about the same speed as current algorithm
 - Shows promise, but V1 produces lower quality reconstructions

PerEvent


perEvent

Entries

Mean

Std Dev

ADC



Fit Quality (Amplitude * R^2)

Gauss Qu

Entries

Mean

Std Dev

Run gaussian fit in time for channels that pass filter

