

修改1:



文件位置: \wsl.localhost\Ubuntu-18.04\home\darren\MYD-JX8MP\L5.10.9\myd-jx8mp_linux_5.10.9\04-Source\myd-jx8mp-yocto\sources\meta-myir\meta-sdk\dynamic-layers\qt5-layer\recipes-fsl\packagegroup

CSDN让我删除的我也没办法 \${@bb.utils.contains('DISTRO FEATURES', 'wayland', 'nxp-demo-experience', '', d)}\

修改2:



```
qtmultimedia \
qtvirtualkeyboard \
fonts \
tf-upgrade \
sqlite3\
# nxp-demo-experience \
"

BB 文件

F 82, 列 27 | 26 个字符, 共 2,27 | 100% | Unix
```


nxp-demo-experience \

重新编译uboot

git clone https://github.com/MYiR-Dev/myir-imx-uboot.git -b develop_2020.04

new file: nxp-experience.text


 $\label{localhost} $$ \sl. localhost \ubuntu-18.04 \normalfont \n$



 $\label{localhost} $$ \sl = 18.04 \rightarrow \sl = 18.04 \rightarrow \sl = 18.04$

本地址

#UBOOT SRC ?= "ait://aithub.com/MYiR-Dev/mvir-imx-uboot.ait;protocol=https"



yir/meta-bsp/recipes-bsp\$ ls/octo\$ cd myir-imx-uboot alsa-state firmware-gca imx-kobs imx-sc-firmware imx-test imx-vpu imx-vpu-hant o-vc sse2neon

firmware-imx-imx-atf223063imx-mkimage imx-seco imx-vpu-hantro isp-imx imx-uuc u-boot

darren@DArren:~/MYD-JX8MP/L5.10.9/myd-jx8mp_linux_5.10.9/04-Source/myd-jx8mp-yocto/sources/metayir/meta-bsp/recipes-bsp\$ cd u-boot

darren@DArren:~/MYD-JX8MP/L5.10.9/mvd-ix8mp linux 5.10.9/04-Source/mvd-ix8mp-vocto/sources/metavir/meta-bsp/recipes-bsp/u-boot\$ ls

u-boot-common.inc u-boot-imx_2020.04.bb u-boot-imx-mfgtool_2020.04.bb u-boot-tools_%.bbappend darren@DArren:~/MYD-JX8MP/L5.10.9/myd-jx8mp_linux_5.10.9/04-Source/myd-jx8mp-yocto/sources/metavir/meta-bsp/recipes-bsp/u-boot\$ ls

u-boot-common.inc u-boot-imx_2020.04.bb u-boot-imx-mfgtool_2020.04.bb u-boot-tools_%.bbappend darren@DArren:~/MYD-JX8MP/L5.10.9/myd-jx8mp_linux_5.10.9/04-Source/myd-jx8mp-yocto/sources/metavir/meta-bsp/recipes-bsp/u-boot\$ vi u-boot-imx_2020.04.bb

darren@DArren:~/MYD-JX8MP/L5.10.9/myd-jx8mp_linux_5.10.9/04-Source/myd-jx8mp-yocto/sources/metavir/meta-bsp/recipes-bsp/u-boot\$