



AVEUC

College Brown Structure

30 Ck2* 0100 d

Products

PROFILE

PROCESS DIMMER

1

INSTERNED INTO W

Description/Specification of Materials	Approximate Dimension	Qty.	Unit Price	Total Price
FULLY COVERED FOOD WARMER (8	HALF-SIZE FOOD PANS)			
-8 half size pans free @ 2" depth -Floor Type	57" (L) x 28" (W) x 50" (H)	10 units	P 78,000.00	P 780,000.00
-Fully Covered Design		100		
-Front Slant Sneeze Guard (Clear		1 1 %		
glass @ 1/4"		2		
thk.)		1 10		
-Tray Slide		. 22		
-Middle Shelf and Top Shelf				
-Stainless Front Cover				
-Ss 304 1.0 thk. Hairline finished		5 201		
Stainless		1 1		
Sheet		5		
-Ss 304 Pipe @ 1" Ø x 1.2mm.thk		3		
-Ss 304 Tubular @ 1/2" x 1/2" x		-		
1.2mm thk.		1 9 5		
-Clear Glass @ 1/4" thk.		10		
-Heavy Duty U-Type Heater @				5
2000W		0		31
-Thermostat @ 300 °C		- H		3 3
-Terminal Lug (Ring type and Clip		1100	FI	B 3
type)		1 2 0	14	2 5
-Toggle Switch		1 22	2	공돌
-Pilot Light (Green)	j !		T Table	E 8
-Two (2) pcs. Tubular Lamp @			0	8 8
15W x 4ft.(L)			0.1	0.0
-Safety Breaker 20amp		181	100	
-heavy duty Caster Wheel		7	LU	
DELIVERY FEE			5	0
TOTAL AMOUNT			7.0	P 780,000.00

- LEAD TIME is twenty (40) working days upon receipt of P.O.
- WARRANTY: One (1) year warranty for FACTORY DEFECT only. Warranty is not covered if the result of inspection was negligence by the customer.
- UNPRODUCTIVE MOBILIZATIONS will be charged to the account of the customer at a fixed daily rate
 of P2,000 for NCR and P4,000 outside Metro Manila on top of the original quote. It is also
 understood that the same rate (excluding cost of materials to be replaced) will apply for after sales
 warranty claims if after diagnosis, cause of damage is neither due to product defect, a false alarm
 nor to faulty workmanship.