

$\text{CO}_2=0.98$, $\text{H}_2=0.003605$, $\text{Ar}=0.006071$, $\text{N}_2=0.000595$, $\text{CH}_4=0.009525$, $\text{H}_2\text{S}=0$

