

$\text{CO}_2=0.98$, $\text{H}_2=0$, $\text{Ar}=0.007502$, $\text{N}_2=0$, $\text{CH}_4=0.00854$, $\text{O}_2=0.003958$, $\text{CO}=0$, $\text{H}_2\text{S}=0$

