

$\text{CO}_2=0.96$, $\text{H}_2=0$, $\text{Ar}=0.015005$, $\text{N}_2=0$, $\text{CH}_4=0$, $\text{O}_2=0.017079$, $\text{CO}=0.007916$, $\text{H}_2\text{S}=0$

