

If after normal cleaning and/or scraping processes a particular code is unreadable or inaccessible, carry on as if no exact match can be found.

If the flow chart leads to a non catalyst test then carry out that test.

If the flow chart leads to a catalyst test to default limits, then carry out that test, but use the less demanding of either the default limits or the specific limits for any vehicle which is an exact match in everything but an unreadable code.

The M.O.T. Inspection Manual Issue Date 01 January 2012