Description: Clarify to the customer that sometimes the scanning bar may remain stuck at 94% or 99% for a couple of minutes. However, the tool is still working.							
The module name might change even if the percentage doesn't. Advise patience until scanning is complete.							

Created/Update Date

T/N #

23-7111-010

1. Initial Confirmation:

Title

Tool #

7111

Confirm with the customer that the tool is getting stuck at 99% during vehicle testing. Note: This could be a hardware issue.

2. Identify the Scenario:

- a) Scenario 1: If the 7111 tablet uses NXP VCI:
- Recommend considering a hardware change to ST VCI.
- b) Scenario 2: If the tablet has ST VCI:
- Proceed to the next step.

Step-by-Step Guide for Troubleshooting SDS 7111 Stuck at 99%

Creator

David G.

3. Check Tool Software Status:

Ask if the tool's software is up-to-date.

If not, find out the message displayed when attempting to update.

4. Gather Vehicle Information:

(Especially if the information is based on a phone call)

Obtain the VIN# or Year, Make, Model, and Engine Size. Add the vehicle data using the CSR system by selecting "Add New Vehicle".

5. Collect OBD Communication Details:

- a) Diagnostic:
- Determine the method selected.
- b) ECU/System:
- Identify the chosen system or module.
- c) Functions:
- Determine the specific functions attempted.

6. Note Vehicle Status:

- a) Ignition Method:
- Identify the ignition state.
- b) Error Message:
- Record any ignition-related error messages.

7. Document Hardware Information:

Capture Tool Name, Tool ID, Tool GUID, and versions for FW, BL, and DB.

8. Consider Model Limitations:

If the SDS 7111 model is 02D0, be aware that the tablet may have limited update capabilities. Alternate Scenario: If the SDS 7111 model is 02D0, inform the customer that the tool might be restricted to older Software and Firmware for VCI, potentially causing scan completion issues.

9. Warranty & Repair Assessment:

If within one year of purchase: Confirm warranty and gather customer details. If beyond one year: Advise on potential repair costs.

Collect customer's name, address, email, and provide shipping instructions if needed.

Conclusion:

Express gratitude to the customer for their cooperation. Inform them of a typical turnaround time of around 7 business days. Encourage them to reach out with further questions or concerns.