
	Tool #	7111	Creator	David G.	Created/Update Date		T/N #	23-7111-004
--	--------	------	---------	----------	---------------------	--	-------	-------------

Description: The purpose of this guide is to assist you in resetting the Oil Warning Light through the Innova 7111 Tablet after an oil change or filter replacement.




Turning off the Oil Warning Light using Innova 7111 Tablet

Title


Condition:

The Service Oil Light is illuminated on your dashboard, indicating that your vehicle requires an oil change or filter replacement.




Step 1: Prepare for Reset

- 1.Turn on the ignition (without starting the vehicle) to power the vehicle's systems.
- 2. Power on the Innova 7111 scanner.
- 3. Connect the scanner to your vehicle's OBD2 port.
- 4. Wait for the Innova 7111 to detect your vehicle.
- 5.On the scanner's menu, select 'Workshop Tools.'



Step 2: Select Oil Light Reset Function

1. Within the 'Workshop Tools' menu, locate and select the function named 'Oil Light Reset.'




Step 3: Confirm Reset

- 1.A pop-up message will appear asking for confirmation to perform the reset.
- 2. Select 'Yes' to confirm and proceed with the reset.



Step 4: Wait for Completion

1. The reset process will begin. Wait for a few seconds while the service is in progress.



Step 5: Check Oil Warning Light

- 1.Once the process is complete, your service is successful.
- 2.Check your vehicle's dashboard to ensure that the Oil Warning Light has turned off.