#### Computer Compass Mk9

### Rectangular plug

```
/ 01 02 03 04 05 06 07 \
|08 09 10 11 12 13 14 15 16 17|
| 18 19 20 21 22 23 24 25 26 27 28 29 |
|30 31 32 33 34 35 36 37 38 39 40 41 42|
| 43 44 45 46 47 48 49 50 51 52 53 54 |
|55 56 57 58 59 60 61 62 63 64 65 66 67|
```

1 Link 1-2	Common
2 Link 1-2	Common
3 Link 3-4	115V 400~
4 Link 3-4	115V 400~
5	
6	
7	
8	
9 Link 1-2	Common
10 Link 10-21	115v 400~ power input
11 Link 1-2	Common
12	Fluxgate input a
13	Fluxgate input b
14	Fluxgate input c
15	9
16 3.8 ohm to Link 1-2	
17	
18	Chassis – ground
19	Heading #1 excite output a
20	
21 Link 10-21	115V 400~
22 Link 1-2	Common – Meter output b
23	inhibit relay contact output a
24	inhibit relay contact output b
25	
26	Meter op a / inhibit input a
27	slave inhibit input a
28	
29	



30 31 Link 1-2 32	22.3V 400~ Fluxgate excite output a Common - Fluxgate excite output b
33	Heading #3 excite input a
34 35	
36	
37	
38	Llooding #2 states sutput a
39 40	Heading #3 stator output a
41	Heading #1 stator output a
42	Gyro stator input a
43	Heading #3 excite input b
44	·
45	
46 47	
48	
49	
50	Heading #3 stator output b
51	
52 53	Heading #1 stator output b
54	Gyro stator input b
55 56	Heading #1 excite input b
57	
58	
59	
60	
61 62	
63	
64	Heading #3 stator output c
65	
66	Heading #1 stator output c
67	Gyro stator input c

Test sockets	
	01 02 03 04 05 06 07     08 09 10 xx 11 12 13
1 2	Gyro input a Gyro input b
3	Gyro input c
4	test switch input a
5	Meter drive output a
6	Meter drive output b
7	test switch input b
8	Flux gate excite a – 0v
9	Flux gate excite b – 22.5v 400~
10	Common
11 4.6v DC	?
12 4.6v DC	?
13 300v DC	?



### Round socket

no I,O,Q,i pinholes



27v 400~ derived from 115v~ input 16v DC

Α В С D Ε F G Н J Κ L М Ν Р R S

U V W X Y

Т

Z a

b c

d e

f g h

j