

[illegible]

The diagram shows the ISL85410FRZ voltage regulator circuit. The input is 24V, which is connected to the VIN pin (pin 4) through a 220uH inductor (L1) and a 75k resistor (R20). The input capacitor (C5) is 4.7F/50V. The output is connected to a 27pF capacitor (C9) and a 75k resistor (R19). The feedback network consists of a 100nF/50V capacitor (C7) and a 75k resistor (R22). The output capacitor (C8) is 1uF/10V. The output voltage is 5.1V.

Address - b1010000

+3V3

GND

U4 24LC128T-1/SN

I2C1_SDA

I2C1_SCL

EEPROM_WP

[illegible]

The schematic diagram illustrates the wiring for the ESCON Driver hall counter. It shows two motor drivers, J11 and J10, connected to a 24V supply. The 5V_HALL supply is connected to the 5V_HALL pin of J11 and the 5V_HALL pin of J10. The 5V_HALL supply is also connected to the 5V_HALL pin of the 5V_HALL regulator, which is connected to the 5V_HALL pin of the 100nF/50V capacitor (C2). The 330 ohm resistor (R11) is connected between the 5V_HALL supply and the 5V_HALL pin of the 100nF/50V capacitor. The 100k resistor (R25) is connected between the 5V_HALL supply and the 5V_HALL pin of the 100nF/50V capacitor. The 10k resistor (R6) is connected between the 5V_HALL supply and the 5V_HALL pin of the 100nF/50V capacitor. The 100 ohm resistor (R7) is connected between the 5V_HALL supply and the 5V_HALL pin of the 100nF/50V capacitor. The 330 ohm resistor (R5) is connected between the 5V_HALL supply and the 5V_HALL pin of the 100nF/50V capacitor. The 150060B555040 diode (D4) is connected between the 5V_HALL supply and the 5V_HALL pin of the 100nF/50V capacitor. The 2N7002 MOSFET (Q3) is connected between the 5V_HALL supply and the 5V_HALL pin of the 100nF/50V capacitor. The LID_Sensor is connected between the 5V_HALL supply and the 5V_HALL pin of the 100nF/50V capacitor. The Magnet input is connected to the 5V_HALL supply and the 5V_HALL pin of the 100nF/50V capacitor. The Magnet input is HIGH when the magnet is present and LOW when it is absent.

[illegible]

J16 Conn_01x08

- Pin 1: +5V +3V3
- Pin 2: MCU_RST
- Pin 8: GND

J17 Conn_01x06

- Pin 1: LCD_RD_D0
- Pin 2: LCD_WR_DO
- Pin 3: LCD_RS_DO
- Pin 4: LCD_CS_DO
- Pin 5: LCD_RST_DO
- Pin 6: GND

J14 Conn_01x10

- Pin 5: SPI1_CLK_SD
- Pin 6: SPI1_MISO_SD
- Pin 7: SPI1_MOSI_SD
- Pin 8: SPI1_CS_SD
- Pin 9: LCD_D1_DO
- Pin 10: LCD_D0_DO

The diagram illustrates the wiring for three Hall sensors (J12, J13, J14) in a motor control system. J12 is connected to Motor_1, Motor_2, and Motor_3. J13 is connected to Motor_Feedback and GND. J14 is connected to HALL_1, HALL_2, and HALL_3.

8