









## Add PWM filter??

Also experiment with the fan. It may not be able to be driven by PWM.

