

Risk Assessment No: P012		Task: Static Fuel Bowser						
Prepared By: Derick Bibby		Date: 21.08.2025			RA Review Date: 20.08.2026			
		Reviewed By: Lee Hardy			Date: 21.08.2025			
PPE: Safety Footwear, High Visibility Jacket, High Visibility Trousers, Hard Hat, Gloves								
Hazard	Persons at Risk	L	S	R	Control Measures	L	S	R
Collision with persons, vehicles, or property while bowser being loaded/unloaded at site	Operative Site personnel Pedestrians	3	5	15	- Ensure that there is sufficient clearance between the bowser and any obstruction (property, vehicles etc.) - If required, a slinger/signaller will be present during loading/unloading. - Clear segregation to mark all pedestrian routes from plant work areas - Where this is not possible, all persons to notify operator upon approach to plant, prior to entering work area. This must be by way of 'thumbs up', which will be instructed to all personnel and visitors upon site induction.	1	5	5
Equipment failure	Operative Site personnel	3	2	6	- All-round checks must be done before start of work each day. These will include general condition of bowser, leaks, spillages and security. - All faults and damage must be recorded on the checklist and reported to Fox Group immediately. - All machinery will be thoroughly inspected before deployment to site, and an inspection certificate will be provided upon delivery.	1	2	2
Incorrect/Unauthorised Use	Operative Site personnel	4	4	16	- Bowser must be kept locked when not in use. - Fox Group supervisor to provide instruction and guidance to personnel on correct use of bowser (mechanical, battery powered etc).	1	4	4

COSHH & Environmental Hazards	Operative Site personnel Pedestrians	4	4	16	- Bowser will be bunded to a minimum of 110% capacity. - Where possible, refuelling of machines should be done in a designated area, a minimum of 10 metres away from water courses and drains, and a minimum of 50 metres from any borehole. - Refuelling must be undertaken carefully, ensuring drip trays are used to catch any spillages. - Always wear gloves when handling any fuel or oils. - Spill kits will be provided with fuel bowser and will contain sufficient material to contain a refuelling spillage. - Report all spillages immediately	2	4	8
Slips, Trips and Falls	Operative	3	3	9	- Bowser to be positioned on flat, solid ground. - Bowser to be positioned in area with sufficient lighting, to allow operatives to see their way around bowser and avoid potential trip hazards. - Boots must be in good condition, with sufficient grip on the sole.	2	3	6
Fire	Operative Site personnel	2	4	8	- No smoking near any fuel bowser or refuelling operations. - All machinery to be switched off while refuelling takes place. - If smell or see smoke, report to Fox Group foreman/supervisor immediately. - Fire extinguisher to be positioned next to bowser.	1	4	4