

Risk Assessment No: WP-004				Task: Screens — Operation, Blockage Clearance and Media Change (scalping, sizing, rinsing)							
Prepared By: Derick Bibby				Date: 02.08.2026				RA Review Date: 01.08.2027			
				Reviewed By: Lee Hardy				Date: 02.08.2026			
PPE: Safety Footwear, High Visibility Jacket, High Visibility Trousers, Hard Hat, Gloves, Ear Defenders, Mask, Eye Protection											
Hazard	Persons at Risk	L	S	R	Control Measures	L	S	R			
Trapped fingers / hand injury during screen media change	Maintenance	4	4	16	- Full LOTO of screen, feed and discharge conveyors before any deck access. - Two-person lift of screen panels; correct pry-bar technique — briefed at toolbox talk. - Cut-resistant gloves and safety glasses at all times during media handling. - Never work above a running screen; deck access under permit only.	1	3	3			
Fall from screen deck / overreach at screen edge	Maintenance	3	4	12	- Fixed guardrails around screen decks to BS EN ISO 14122. - Rescue plan and rated harness for work outside fixed rails. - No deck access during operation. - Toe-boards to prevent tools being kicked over the edge.	1	4	4			
Entanglement — drums, drive shafts, couplings, take-up assemblies	Operator Maintenance	4	5	20	- Fixed guards on all drums, drives, couplings and take-up assemblies. - Belt-tracking adjusted from external take-up handles only. - Full LOTO before removing a guard, freeing a jammed belt or cleaning drums. - Signage “Guard must be in place before start” at each drum.	1	5	5			
Contact with moving parts (drives, drums, agitators, augers)	Operator Maintenance Contractors	4	5	20	- Fixed guards to BS EN ISO 14120 secured with tooled fasteners. - No guard removed unless the machine is locked off in accordance with FoxSafe Isolation & Lock Out Procedure. - Emergency stops and pull-cord trip wires within reach; tested weekly. - Daily start-up checklist CL-WP-01 confirms all guards in place before running. - No loose clothing, jewellery or long hair uncovered.	1	5	5			
Manual handling of screen media, cloths, cyclone parts, hoses	Maintenance Operator	4	3	12	- Task-based manual handling assessment for screen cloths, cyclone apex and filter-press cloths. - Mechanical lifting (chain block, telehandler, MEWP with man-basket) for loads > 20 kg. - Two-person lift protocol for awkward items. - LOLER-inspected lifting accessories only.	2	2	4			
Noise exposure ≥ 85 dB	All plant personnel	4	3	12	- Noise survey identifies zones ≥ 85 dB — mandatory hearing protection signage. - Ear defenders SNR ≥ 27 dB issued and worn in mandatory zones.	2	3	6			

					• Audiometry health surveillance for staff regularly on the plant footprint. • Noise-reducing enclosures maintained where fitted; damaged panels reported.			
Exposure to respirable crystalline silica (RCS) and other dusts	Operator Picking staff Loader driver	4	4	16	• Plant runs wet — spray bars on scalping and sizing screens for suppression. • Water suppression at feed hopper and stockpile transfer points. • FFP3 mask when dry-handling filter cake or working downwind of dust sources. • Air-conditioned cabs with positive-pressure filtered air on all mobile plant. • Personal RCS monitoring on rolling programme under health surveillance. • No dry-sweeping — vacuum or damp-down only.	2	4	8