

Risk Assessment No: WP-009				Task: Conveyors & Stockpile Discharge							
Prepared By: Derick Bibby				Date: 02.08.2026			RA Review Date: 01.08.2027				
				Reviewed By: Lee Hardy			Date: 02.08.2026				
PPE: Safety Footwear, High Visibility Jacket, High Visibility Trousers, Hard Hat, Gloves, Ear Defenders, Mask, Eye Protection											
Hazard	Persons at Risk	L	S	R	Control Measures				L	S	R
Entanglement in conveyor belt, rollers or drums	Operator Maintenance	4	5	20	- Fixed guards on all drive drums, tail drums, coupling shafts and take-ups. - Rip-cord (pull-cord) trip wires along the length of every conveyor; tested weekly. - Full LOTO before removing a guard, clearing spillage under a belt or freeing a jam. - Belt-tracking adjustment via external take-up handles only. - No reaching into belt/drum interface — signage at each drum.				1	5	5
Stockpile collapse / engulfment	Loader driver Ground staff	3	5	15	- Stockpile geometry maintained within safe angle of repose. - No excavation under a stockpile face — loader operates from top-down or safe stand-off. - No pedestrian access to active stockpile pick-up area — segregated zone. - Stockpile height limited per site-specific geotechnical assessment.				1	5	5
Work under stockpile conveyor — falling material	Maintenance Cleaners	3	4	12	- Isolate conveyor and preceding feed before any work beneath. - Helmet with chin-strap mandatory. - Segregation and signage to prevent unauthorised entry beneath a running conveyor. - Spillage cleaned only when the belt is locked off.				1	4	4
Struck by mobile plant (wheel loader, telehandler, tipper wagons)	Operator Loader driver Wagon drivers Visitors	4	5	20	- Traffic Management Plan segregates pedestrians from mobile plant. - Wheel loader fitted with reversing alarm, camera and beacons. - Wheel-stops at feed hopper; banksman when reversing at hopper. - Radio protocol between wash-plant operator and loader driver. - Visitors escorted at all times; hi-vis and site induction mandatory.				1	5	5
Slips, trips and falls on the same level	All plant personnel	4	3	12	- Anti-slip walkways and stair-treads; wash-down at end of shift. - No trailing hoses or cables across walkways — stored on reels or coiled. - Immediate clean-up of oil, hydraulic fluid or fines spillage. - Adequate task lighting throughout the plant. - Correct footwear with slip-resistant sole to SRC.				2	3	6
Exposure to respirable crystalline silica (RCS)	Operator Picking staff	4	4	16	Plant runs wet — spray bars on scalping and sizing screens for suppression.				2	4	8

and other dusts	Loader driver				• Water suppression at feed hopper and stockpile transfer points. • FFP3 mask when dry-handling filter cake or working downwind of dust sources. • Air-conditioned cabs with positive-pressure filtered air on all mobile plant. • Personal RCS monitoring on rolling programme under health surveillance. • No dry-sweeping — vacuum or damp-down only.			
Noise exposure ≥ 85 dB	All plant personnel	4	3	12	• Noise survey identifies zones ≥ 85 dB — mandatory hearing protection signage. • Ear defenders SNR ≥ 27 dB issued and worn in mandatory zones. • Audiometry health surveillance for staff regularly on the plant footprint. • Noise-reducing enclosures maintained where fitted; damaged panels reported.	2	3	6