FreeCad TD 3

Partie fabrication CNC

Workbenchs utilisés

Path

Tutoriels

Manuel:

https://wiki.freecadweb.org/Manual:Preparing models for 3D printing#Generating G-code

Path Walkthrough for the impatient:

https://wiki.freecadweb.org/Path_Walkthrough_for_the_Impatient

Path Module part 1 and 2:

https://www.youtube.com/watch?v=5Lj4wEmdOwQ

https://www.youtube.com/watch?v=V0VsGI6WOFI

Consignes

Produire le .gcode pour réaliser la pièce du 6ème exemples de FreeCAD















