



ENSURE ALL SHARP EDGES ARE BROKEN USE HOLES FOR PRIORITY ALIGNMENT WELD AS NEEDED UNLESS SPECIFIED





