## List of small tools required and their prices.

**Author:** Isaac Newton

Source: MINT 19/2/400, National Archives, Kew, Richmond, Surrey, UK

<400r>										
	<b>t</b> b	q <sup>r</sup>	li		<4001 <sup>-</sup> S		Ιħ	S	d	
For A Plate & Cradle {q	t <sub>}</sub> 1:	-		at	28	per cwt			9	
for a pair of Bellows & Leaden				at		1		0:	0	
-	t} 0:	2.	21				1:	10:		
				at						
for 9 moulds & Boards at 5 <sup>s</sup> Ea							:	:	0	
for 18 pairs of Screws at 2: 6 a	pair						:	:	0	
for A Sand Trough & Closing Board								:	0	
for 2 Loads of Sand & making							:	:	6	
for A Coale Trough & Spilling	Troug	h					:	:	0	
for Bricks & building of the Fu	rnace						:	:	0	
for Iron head to the moulds {q	t} 0:	2:	0	at	$4^{\frac{1}{2}}$		1:	1:	0	
for 1 hundred of melting Potts a	ıt 7 <sup>d</sup> p	er pi	ece				2:	18:	4	
for a Chalde of Coales							1:	12:	0	
for Tiles and mill dust							0:	10:	0	
for 1 large pair of Sheers & 1 lesser pair of sheers for Brushes & for the moulds fr 6 <sup>li</sup> : of wire. a large Iron Anvile to break the metle. 2 pair of hand Tongues: 2 hand Bowles. 1 Sett of Pattarnes: 1 Sledge hammer & 1 hand hammer. 2 Washing Tubbs. 2 Shoviles 2 Wire Sives. 1 Washing Bowle										
1 large Tray: & 1 lesser Tray all which comes to								31: 19: 8		