
IRRIGATION SYSTEM REHABILITATION

ENVIRONMENTAL MITIGATION REPORT (EMR)

PRESENTATION PLAN

- BACKGROUND (EXISTING CONDITIONS)
- POTENTIAL IMPACT AND MITIGATION MEASURE
- □ ENVIRONMENTAL MONITORING AND EVALUATION TRACKING TABLE

DUPIN IRRIGATION SYSTEM MAP



HIGHEST WATER COLLECTION POINT

Dam made of stone, stems, hay, and dirt



LOWER WATER COLLECTION POINT

Right bank canal

Mayard River bed

Barrage made of stones



SURROUNDING HILLSIDE COMPLETELY DEFORESTED...

Potential risk of erosion damage to irrigation system



... AS ALL SURROUNDING MOUNTAINS TOP ARE COMPLETELY DEFORESTED...



HYDROLOGICAL EROSION, A CONSTANT THREAT TO THE SYSTEM

Erosion of all types is threatening irrigation structures (here gully formation)



... HOWEVER FOREST TREES COVERED THEM ONCE

Forest compose of more than 20 different tree species covered these mountains at the beginning of the past century. Some of the more frequent species were

WATER DISTRIBUTION

First secondary canal (to Mayard)

Primary canal

Rudimentary rock door



REMAINING DISTRIBUTION DOORS

Last existing metallic doors are linking badly



SOME CROPS GROWN ON THE PERIMETER

