

A001-SEC-2026-08 - A-001 Security Posture Review, August 2026 (APPROVED)

Synthetic training document. Not for operational use.

Document ID: A001-SEC-2026-08 | Version 1.0 | Status: APPROVED | Effective: 2026-08-25 | Owner: Plant Cyber Security | Asset: A-001 (Pump 001, Cooling Water, unit TRN-A)

1. Summary

A-001 is classed Critical and has Restricted network exposure. Its last security review was on 2026-01-23, which is 214 days before this review and past the 180-day target. Patch status is Overdue and the access risk flag is Yes.

2. Open vulnerabilities

ID	Issue	CVSS	Due	Status
SYN-2026-0169	Outdated firmware on condition-monitoring gateway	7.8	2026-07-29	Open, overdue
SYN-2026-0170	Default credentials on local HMI	8.2	2026-08-06	Open, overdue
SYN-2026-0171	Remote vendor session without recording	4.6	2026-09-05	In remediation

Remediation targets follow SEC-PROC-PATCH-001 Version 2.0 (High within 14 days).

3. Access

Nine accounts reach the gateway; three are privileged, one is a shared vendor account without MFA, and two are stale. The last access review was 2026-01-31.

4. Incidents and alerts

- SEC-INC-0041 (2026-07-30, High, Contained): off-hours vendor session through the shared vendor account without MFA. A controller setpoint change under ticket CHG-0412 ran outside the change window.
- SEC-INC-0040 (2026-08-14, Medium, Open): 34 failed logins from one external address within about 20 minutes. No successful login from that address is recorded.

5. Operational context

Health score 68.05 (risk MEDIUM), three urgent open work orders, and anomaly flags on vibration from 2026-08-18. The logs reviewed do not connect any external address to a controller change. Any cause of the vibration is an engineering question.

6. Evidence gaps

- The ticket CHG-0412 has no recorded approval inside the change window.
- One alarm-threshold update on 2026-08-17 had no ticket and was closed as a false positive without a recorded reason.
- Sensor detail beyond hourly data is not available for the gateway itself.

7. Human next step

The Plant Cyber Security lead, with the A-001 engineering owner and the shift supervisor, decides on remediation timing, any access change and any isolation. This review does not authorise any of these.