

SUPRA QUALITY EXPORTS (I) PVT LTD

A-92,Road No. 16,
Wagle Industrial Estate
Thane west-400604
India

S/DIR/34 Rev.12 26/08/25
Phone : 45196493/94/95/96
Email:quality@supraexports.in

DIMENSIONAL INSPECTION REPORT

Part Description:- S.S. flange

Part No:- FATI 035

C.P.O.:-

Order Date:-

Order Qty:-

Vendor Name:- Pentagon

S.P.O: SQPO25261597

Order Date:- 17.10.25

Order Qty:- 115

Buyer name:- FATI

DATE:- 18.11.2025

Report No:-2526/0351

ZINC	<input type="checkbox"/>
COPPER	<input type="checkbox"/>
NICKEL	<input type="checkbox"/>
NICKEL CHROME	<input type="checkbox"/>
TIN	<input type="checkbox"/>
Un-plated	<input checked="" type="checkbox"/>

MATERIAL GRADE:- SS-304

SR NO	SAMPLE PARAMETER	1	2	3	4	5	6	7	8	9	10	REMARK
1	A1F -0.25 90.00	89.96	89.96	89.92	89.96	89.94	89.90	89.94	89.92	89.96	89.92	OK
2	Φ 89.00 ±0.3	89.02	88.96	88.96	88.94	89.02	89.04	89.02	88.98	89.02	89.06	OK
3	Φ 72.00 ±0.3 Gauge +0.03	71.92	71.96	71.94	71.94	71.90	71.96	71.94	71.96	71.94	71.90	OK
4	CHF ±0.3 90.00	89.96	89.96	89.94	89.96	89.98	89.96	89.94	90.00	89.98	89.96	OK
5	20.00 ±0.2	20.04	19.96	20.01	19.99	20.07	20.03	20.04	20.04	20.02	19.98	OK
6	12.00 ±0.2	12.02	12.04	12.03	12.04	12.05	12.01	11.97	11.98	12.03	12.02	OK
7	1.50 max	1.37	1.39	1.36	1.35	1.34	1.36	1.34	1.36	1.37	1.39	U/S O.06
8	2.50 ±0.1	2.51	2.52	2.54	2.52	2.50	2.54	2.51	2.51	2.54	2.54	OK
9	Anse 30°	30°					30°				30°	OK
10	G 2 1/2 BSP Major -0.034	Check with Gauge	Go	BNC	413	Not Go	B+F	777				OK
11	75.184	74.94	74.96	74.92	74.96	74.92	74.90	74.92	74.98	74.96		OK
12	Pitch -0.034	73.54	73.49	73.49	73.54	73.52	73.49	73.56	73.51	73.55	73.48	OK
13	CHF 2x45°	-	-	-	2x45°	-	-	-	-	-	-	OK
14	Anse 45°	-	-	-	45°	-	-	-	-	-	-	OK
15	Engraving											
16	SS 304 - SQE 033 1125											
17	G 2-1/2"											
18												
19												
20												

CHECKED BY:- Scammi

APPROVED BY:- Patel

SIGN & Dt:- Patel 18/11/25

DATE:- 20-11-25

PREVIOUS DATE :

PREVIOUS REPORT NO :

RECEIVED QTY

LOT 1	:	115	nos.
LOT 2	:		nos.
LOT 3	:		nos.
LOT 4	:		nos.

REMARK : 1) Thread & Sharp Edges Damage of Surface area Scratch Marks
 2) Obs.
 3) Damage Rework
 4)
 5)