

SUPRA QUALITY EXPORTS (I) PVT LTD

A-92,Road No. 16,
Wagle Industrial Estate
Thane west-400604
India

S/DIR/34 Rev.12 26/08/25
Phone : 45196493/94/95/96
Email:quality@supraexports.in

ZINC	<input type="checkbox"/>
COPPER	<input type="checkbox"/>
NICREL	<input type="checkbox"/>
NICKEL CHROME	<input type="checkbox"/>
TIN	<input type="checkbox"/>
Un-plated	<input type="checkbox"/>

DIMENSIONAL INSPECTION REPORT

Part Description:- M5 Stud

Part No.: 571435900

C.P.O.:-

Order Date:-

Order Qty:-

Vendor Name:- Real Tech

S.P.O: SQPO2526 0808

Order Date:- 11/07/2025 Order Qty:- 2500

Report No.: 25/08/2025

Buyer name:- ZOPPAS ROMANIA DATE:- 08/09/2025

Report No.: 25/

MATERIAL GRADE :-

SR NO	SAMPLE PARAMETER	1	2	3	4	5	6	7	8	9	10	REMARK
1	M5	54.72	54.89	54.91	54.54	53.91	54.86	54.74	54.82	54.06	55.12	VIS
		54.68	54.87	54.90	54.53	53.89	54.80	54.67	54.77	55.04	55.10	OK
2	Ø6	6.016	5.986	6.018	6.035	6.007	6.061	5.969	5.991	5.994	5.969	OK
		5.980	5.983	6.007	6.020	5.988	6.056	5.968	5.983	6.003	5.982	OK
3	16	16.12	16.10	16.04	16.03	16.03	16.02	16.07	16.10	16.08	16.15	OK
4	1.00	0.96	0.97	0.98	0.99	0.99	0.98	1.03	1.01	0.98	0.99	OK
5	Ø8.7	8.701	8.705	8.707	8.701	8.703	8.708	8.696	8.701	8.703	8.708	OK
6	Ø0.8	0.73	0.81	0.82	0.77	0.79	0.79	0.81	0.73	0.81	0.76	OK
7	0.8	0.79	0.73	0.75	0.75	0.74	0.74	0.72	0.71	0.71	0.72	OK
8	3° ± 0.5°	3°	3°	3°	3°	3°	3°	3°	3°	3°	3°	OK
9	8	7.75	8.50	7.86	8.24	6.85	7.42	8.34	8.23	6.10	8.43	VIS 0.15 0.95±0.30
10	M4	Checked with TPin M4X0.7-6H (NoC PNC 7595) & Nono (PPF 5687)										OK
11	Minor dia. 3.44 ± 0.422	3.44	3.45	3.43	3.45	3.49	3.49	3.52	3.43	3.44	3.45	OK
12	Symbol $\frac{d}{2}$	Visually checked and found OK										OK
13												
14												
15												
16												
17												
18												
19												
20												

CHECKED BY :- Amit

APPROVED BY :- Amit

SIGN & Dt:-


15/09/2025

DATE:- 16/09/2025

PREVIOUS DATE :

PREVIOUS REPORT NO.:

RECEIVED QTY

LOT 1 : 1400 nos.

LOT 2 : 1507 nos.

LOT 3 : nos.

LOT 4 : nos.

REMARK : 1) Total height length not as per requirement. No visible height gauge's pieces found. (100% checked)
 2) Thread length not as per drawing (100% checked done) (Rejected material send to rework)
 3)
 4)
 5)