

PlantMind Demo Environment

Seed data loaded for P-101, C-201 and HX-301

PLANTMIND AI

Industrial Asset Intelligence Dashboard

Maintenance, RCA, compliance, document intelligence and asset knowledge for industrial operations.

DEMO STORY

P-101 is the highest-priority risk asset; C-201 needs compressor maintenance planning; HX-301 needs fouling inspection and cleaning evidence.

Total Assets

3

[Open asset registry](#)

High-Risk Assets

1

P-101

Compliance Gaps

5

High severity: 2

Knowledge Graph

49

78 relationships

OPERATIONS COMMAND CENTER

Live operational priorities

Current asset risk, RCA, compliance, maintenance and audit-readiness signals calculated from the active PlantMind demo dataset.

Generated: 8 Jul 2026, 4:29 am

Assets at Risk

3

Medium, high or critical operational risk

Critical RCA Cases

1

Open high-severity investigations

Compliance Gaps

5

Missing, delayed or overdue controls

Urgent Work Orders

7

Open high-priority maintenance work

Audit Readiness

20%

Missing Evidence

4

Critical

Open gaps without linked evidence

HIGHEST-PRIORITY RECOMMENDED ACTION

Inspect and restore bearing lubrication Immediate

Safely isolate the pump, inspect lubricant condition and quantity, and restore lubrication according to the approved procedure.

Asset: P-101 Owner: Mechanical Maintenance Engineer Confidence: 91% Due in: 4 hours

VERIFICATION REQUIREMENT

Lubrication completed and evidence attached

Open source workspace

Assets at Risk

[View assets](#)

P-101

Cooling Water Circulation Pump

97

High

Health: 3

Sensor: Critical

C-201

Process Air Compressor

56

Medium

Health: 44

Sensor: Warning

HX-301

Feed Preheater Heat Exchanger

56

Medium

Health: 44

Sensor: Warning

Critical RCA Cases

[Open RCA](#)

RCA-P101-001

Critical

P-101 High Vibration and Bearing Temperature Event

Asset: P-101 Status: Open Confidence: 91%

Treat lubrication degradation as the primary cause until lubricant condition, alignment measurements and vibration-spectrum analysis confirm or reject the hypothesis.

Open Compliance Gaps

[View compliance](#)

GAP-001

High

Weekly lubrication check

Asset: P-101 Status: Missing

Evidence missing

GAP-002

High

Work permit before bearing inspection

Asset: P-101 Status: Missing

Evidence missing

GAP-003

Medium

Filter replacement verification

Asset: C-201 Status: Delayed

Evidence linked

GAP-004

Medium

Cleaning and fouling inspection

Asset: HX-301 Status: Overdue

Evidence missing

GAP-005

Medium

Work permit before cleaning

Asset: HX-301 Status: Missing

Evidence missing

Urgent Maintenance Work

Open work orders with high priority or elevated operational risk.

[Open maintenance command center](#)

MWO-P101-001

Critical

P-101

Inspect and relubricate drive-end bearing

Status

Open

Risk score

94

Confidence

93%

Due

21 Jun 2026, 3:15 pm

Owner: Mechanical Maintenance Engineer

MWO-P101-002

High

P-101

Inspect bearing condition

Status

Open

Risk score

88

Confidence

84%

Due

21 Jun 2026, 7:20 pm

Owner: Reliability Engineer

MWO-HX301-001

High

HX-301

Inspect fouling

Status

Open

Risk score

84

Confidence

88%

Due

24 Jun 2026, 7:30 am

Owner: Inspection Engineer

MWO-P101-003

High

P-101

Verify shaft alignment

Status

Planned

Risk score

82

Confidence

84%

Due

22 Jun 2026, 3:25 am

Owner: Rotating Equipment Technician

MWO-HX301-002

High

HX-301

Clean heat-transfer surfaces

Status Planned

Risk score 81

Confidence 86%

Due 25 Jun 2026, 7:40 am

Owner: Mechanical Maintenance Supervisor

MWO-P101-004

High

P-101

Conduct post-maintenance vibration test

Status Planned

Risk score 78

Confidence 91%

Due 22 Jun 2026, 7:30 am

Owner: Condition Monitoring Engineer

MWO-C201-001

High

C-201

Inspect compressor lubrication system

Status Open

Risk score 76

Confidence 81%

Due 23 Jun 2026, 8:00 am

Owner: Mechanical Maintenance Engineer

Asset Health

Current risk and condition summary

3 assets monitored

P-101

High Risk

Risk Score

97

Cooling Water Circulation Pump • Pump

Health Score

3/100

High vibration, bearing temperature warning, abnormal noise, and missing lubrication evidence.

Sensor: Critical

Compliance: High Risk Non-Compliant

Gaps: 2

C-201

Medium Risk

Risk Score

56

Process Air Compressor • Compressor

Health Score

44/100

Decreasing RUL, outlet temperature warning, pressure ratio instability, and delayed filter verification.

Sensor: Warning

Compliance: Medium Risk Non-Compliant

Gaps: 1

HX-301

Medium Risk

Risk Score

56

Feed Preheater Heat Exchanger • Heat Exchanger

Health Score

44/100

Low outlet temperature, high pressure drop, reduced efficiency, suspected fouling, and overdue cleaning evidence.

Sensor: Warning

Compliance: Medium Risk Non-Compliant

Gaps: 2

Maintenance Events

[View all](#)

WO-1002

High

Lubrication Verification

Verify lubrication level and upload missing lubrication evidence

P-101

Due: 2026-01-23

WO-1001

High

Bearing Inspection

Inspect bearing housing due to high vibration and abnormal noise

P-101

Due: 2026-01-24

WO-1003

Medium

Filter Replacement Verification

Verify whether compressor filter replacement was completed

C-201

Due: 2026-02-20

WO-1004

Medium

Compressor Inspection

Inspect compressor due to decreasing RUL trend

C-201

Due: 2026-02-28

WO-1006

Medium

Work Permit Review

Verify work permit evidence before cleaning activity

HX-301

Due: 2026-03-10