3) WAP (recursive func NCR)

```
.model small
.data
n dw 4
r dw 2
ncr dw 0

.code
mov ax,@data
mov ds, ax

mov ax, n
mov bx, r

call ncrpro
call disp
jmp final

ncrpro proc near
cmp ax, bx        ; r = n
je res1
cmp bx, 0         ; r = 0
je res1
cmp bx, 1         ; r = 1
je resn
dec ax
cmp bx, ax
```

```
        je ncr
        push ax
        push bx
        call ncrpro

        pop bx
        pop ax
        dec bx
        push ax
        push bx
        call ncrpro
        pop bx
        pop ax
        ret

res1:   cinc ncr
        ret

incr:   cinc ncr
ren:    add ncr, ax     ; 1+2  3+3 = 6
        ret
ncrpro  endp

disp    proc near
        mov bx, ncr
        add bx, 3030h
        mov dl, bh
        mov ah, 02h
        int 21h
        ret
disp    endp

final:  mov ah, 4ch
        int 21h
        end
```

2) WAP to display count:

```
.Model small
.code
        MOV CL,00
        MOV AH,00H
        MOV AL,03H
        int 10H

BACK :  MOV BH,00H
        MOV DH,00H
        MOV DL,00H
        MOV AH,02H
        INT 10H
```

```
MOV AL,CL
ADD AL,00H
AAM                    ; 0000
ADD AX,3030H           ; 3030
MOV CH,AL
MOV DL,AH
MOV AH,02H
int 21H
MOV DL,CH
MOV AH,02H
int 21H
Call DELAY
INC CL
XOR AX,AX
CMP CL,100D
  JNE BACH
  JE LAST

DELAY   PROC NEAR
 Push AX
 Push BX
 Push CX
 MOV CX,00FFH

AG:   MOV BX,00FFH

AG1:   NOP
 DEC BX
 JNZ AG1
 DEC CX
 JNZ AG
 POP CX
  POP BX
  POP AX
    RET
```

```
        DELAY ENDP

LAST:   MOV AH, 4Ch
        INT 21H
        END
```

prog to place the cursor, (accept x & y coordinate)

```
.model small
disp macro msg
    LEA DX, MSG
    MOV AH, 09H
    int 21H
ENDM

.Data
Row DB 02 DUP (0)
Col DB 02 DUP (0)
```

msg1 DB 0DH, 0AH, "enter x coordinate:$"
msg2 DB 0DH, 0AH, "enter y coordinal:$"
msg3 DB 0DH, 0AH, "cursor placed at correct position$"

• Code

```
MOV AX,@data
MOV DS,AX
DISP MSG1
MOV SI ,OFFSET ROW
CALL READ
 DISP MSG2
MOV SI, OFFSET COL
CALL READ
MOV SI, OFFSET ROW
MOV AH,[SI]
INC SI
MOV AL,[SI]
SUB AX,3030H
AAD
MOV DH,AL
MOV SI,OFFSET COL
MOV AH [SI]
 INC SI
 MOV AL,[SI]
SUB AX,3030H
 AAD
MOV DL,AL

MOV AH,00
MOV AL,03H
INT 10H
MOV AH,00H
int 10H
disp msg3
JMP FINAL
```

```
READ PROC NEAR
    MOV CX,02H

BACK : MOV AH,01H
    int 21H
    MOV [SI], AL
    INC SI
    DEC CX
    JNZ BACK
    RET
READ ENDP

FINAL :MOV AH, 01H
    INT 21H
    MOV AH, 4CH
    int 21H
    END
```