

CONTACT REPORT					
Date:		Consecutive Day of Contact:		Type of Inspection:	
January 18, 2023		Day 3 of 10		Regulatory (Health Canada)	
Subject:		Code:		Site:	
GMP Inspection		cGMP		Signet Campus	
Participant(s)				Total Number of Requests (Cumulative): 172	
Inspectors:	Shannon Paiement, Mithushan Selvakumar			Number of Requests Provided:	168
Apotex Host:	Yoel Diaz Leon, Laura Ralph			Requests < 30 mins:	66
Scribe:	Tam Dang, Rafelina Spizzirri			Request >30 mins < 2 hours:	85
Start Time:		End Time:		Requests > 2 hours:	17
9:00am		4:10pm		Outstanding Requests:	4
Executive Summary					
The inspection commenced at 9:00am and concluded at 4:10pm. The day was spent reviewing documentation.					
Potential Concerns:					
- In the Manual Clean Up Room 2110 at 4100 Weston Rd Packaging, there is no clear delineation between dirty and clean equipment. 285 Garyray Drive site was not included in the Contamination Controls Risk Report based on current containment controls however, the site should not be excluded from the holistic review performed as part of this process.					
Facility Tours:					
None.					
System Demonstrations:					
LIMS demo (Rajiv Punj, Lead Chemist): status of pH buffer reagent lot 2205D21 observed during the lab tour yesterday.					
Document Reviews & SME Discussions:					
- Overview of Manual Cleaning of Equipment at 4100 Weston Road Packaging - Documents pertaining to Water Purification System at 285 Garyray Drive - Overview of QC Qualification and Maintenance of House Reference Standards - Procedures governing the issuance of tooling sets at 285 Garyray Drive - Selected calibration records for 3701 Weston Road QC SP Lab instruments (Dissolution and Thermocouple) - Review of selected LIRs: 1126569, 1198386, 1205497, 1216742 - Review of selected Deviations: 1198846 - Selected Process Validation records for Lenalidomide: S2-PQP-3351-002, S2-PQR-3351-003, S2-PQP-3351-001, S2-PQR-3351-002 - Documents related to BAS qualification and procedure for health checks performed biweekly. - Rationales for time limits of critical (A1) alarms for environmental monitoring. - Quality Risk Management Plan Report – Contamination Controls for Signet campus. - Cardboard contamination controls in Packaging areas at 4100 Weston Road. - Procedure for handling of bottles at the induction sealer and shrinkwrap bundler during line stoppages.					
Documents Taken Off-Site (Print/USB):					
LIR 1126569, LIR 1216742					
Preparation for Next Day:					
- Inspectors will arrive on-site at 9:00am and continue documentation review and SME discussions. - Follow up discussions required for storage of set-up bottles in secondary packaging, documentation of downflow booth operational verification, handling of metal detector waste and selection of blistering tooling and feeding system. - Follow up discussion on requirements to challenge BAS alarms and the supporting data for the 20 minutes time limit for A1 differential alarm.					
Distribution					
Jeff Watson	Andrew McNicoll	Steve Liberty	Pradeep Sanghvi	Kiran Krishnan	Kevin Zive
Peter Hardwick	Gordon Fahner	Peter Eichinger	Mohamed (Mohamed (Mostafa)) Ahmed	Jordan Berman	Sandra Tomassini
Medhanie Tekeste	Joanne Campbell	Martin Ehlert	Darren Hall	Christian Knebel	Hasit Desai
Ramon Martinez	Bhupat Sakaria	Navid Ghamami	Sylvain Thuot	Yoganjaneya Reddy	Parameswaran P S
Jason Fischer	Wilfredo Diaz, Jr.	Cecilia Tapia Noriega	Miguel Angelo Ricchiuti Zubiaur	Ramesh C G	Gorana Lakic
Galina Desai	George Elia	Gabriela Meza Suarez	Carlos Villalobos Robles	Harjinder Brar	John Herrera
Madhu Moosapeta	Angelo Iarrobino	Elizabeth Bagshaw	Jude Vethanayagam	Rob Mancuso	Chelsey Baschuk
Debbie Poon	Denis Rusu	Alma Arzate	Suravanditha PraveenKumar	Michelle Murray	Mark Goneau
Winnie Tong	Joe Fierro	Patrick Logel	Chi Hung	Alex Dukhovny	Vickie Ho
Vijaya Iyer	Mohamed Chan				